





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	ML ML250 BLUETEC AMG SPORT
Colour	Black
Year of manufacture	2014
Top speed	130 mph
0 - 100 km/h	9.0 seconds
0 - 60 mph	9.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

С.	-	200	- 1	
	ш	ľν	/	L

Date	2021-10-08
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-10
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	8
Total items failed	3

MOT #8		2023-09-11 15:47
MOT test	number	504331167158
Result		✓ Passed
Next expi	y date	2024-09-10
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2022-09-08 13:35
MOT test number	314813077581
Result	✓ Passed
MOT #6	2021-09-09 12:19
MOT test number	870604196942
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #5 2021-09-01 10:20

MOT test number 867983495982

Result X Failed

Fail Rear fog lamp not working (4.5.1 (a) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Also completely bald on inner (5.2.3 (d) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Almost bald on inner (5.2.3 (e))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Also COMPLETELY bald on inner and outer (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge COMPLETELY bald on inner, low on outer (5.2.3 (e))

MOT #4 2020-09-02 10:29

MOT test number 870045383019

Result \rightarrow Passed

Advice Rear Inner Brake pad(s) wearing thin Appear to be approx 80% worn (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Wearing low on innermost edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn very low on innermost edge (5.2.3 (e))

MOT #3 2019-04-09 10:31

MOT test number 470674706791

Result \rightarrow Passed

MOT #2 2018-09-05 10:04

MOT test number 157041158763

Result \(\sqrt{Passed} \)

MOT #1 2017-07-26 10:54

MOT test number 401845729767

Advice Rear Tyre worn close to the legal limit Nearside and offside (4.1.E.1)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	10 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

	More info >
Plate changes Cas in this shock if this MEDCEDES DENZ had different average an electron	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK SIZ
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-08-04
Last registration	2023-09-11
Complete history	See info



Registration #1	2014-08-04	6 mi
Registration #2	2017-07-26	30.611 mi
Registration #3	2018-09-05	40.235 mi
Registration #4	2019-04-09	45.195 mi
Registration #5	2020-09-02	59.557 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.777 ea
-		1.77 m
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1926 mm
Height	1788 mm
Length	4804 mm
Wheel base	2915 mm
Kerb weight	2060 kg
Max. allowed weight	2950 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	65196032149152