



report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Silver
Year of manufacture	2004
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	M





Internet history

Entry 2

Date	2022-01-05
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-11-10
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-15
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	11
Total items failed	12
MOT #23	2024-04-16 08:55
MOT test number	848230561434
Result	✓ Passed
Next expiry date	2025-04-15
MOT #22	2023-04-08 14:48
MOT test number	636948617310
Result	✓ Passed
MOT #21	2022-02-08 10:13
MOT test number	345370384553
Result	✓ Passed
MOT #20	2022-01-28 10:03
MOT test number	477325626899
Result	✗ Failed
Fail	Offside Front Headlamp aim too low (4.1.2 (a))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #19**

2021-03-08 08:32

**MOT test number**

172799365210

**Result**

✓ Passed

**Advice**

Vehicle has been stood.

**MOT #18**

2021-03-02 08:52

**MOT test number**

356148454864

**Result**

✗ Failed

**Fail**

Offside Headlamp aim too low (4.1.2 (a))

**Advice**

Vehicle has been stood.

**Fail**

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail**

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #17**

2019-09-09 13:35

**MOT test number**

690216104104

**Result**

✓ Passed

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Plastic covers fitted

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2019-09-06 08:50**MOT test number** 378018305263**Result** ✗ Failed**Advice** Plastic covers fitted**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2018-09-18 11:14**MOT test number** 416425231169**Result** ✓ Passed**MOT #14** 2017-09-21 08:25**MOT test number** 683178517473**Result** ✓ Passed**MOT #13** 2016-09-16 15:23**MOT test number** 834950520617**Result** ✓ Passed**MOT #12** 2016-09-13 12:56**MOT test number** 883081249913**Result** ✗ Failed**Fail** Offside Front Upper Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt outer (2.4.G.2)**Fail** Nearside Front Upper Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt outer (2.4.G.2)**MOT #11** 2015-09-24 14:23**MOT test number** 958190966289**Result** ✓ Passed

**MOT #10** 2014-09-26 11:58**MOT test number** 236099664261**Result** ✓ Passed**MOT #9** 2013-09-24 16:25**MOT test number** 635177263255**Result** ✓ Passed**MOT #8** 2013-09-18 11:19**MOT test number** 747781363240**Result** ✗ Failed

**Fail** Nearside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Notice** All 4 tyres perished

**MOT #7** 2012-09-28 15:26**MOT test number** 827732772247**Result** ✓ Passed**MOT #6** 2012-09-26 11:50**MOT test number** 536060672281**Result** ✗ Failed

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Fail** Offside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #5** 2011-09-27 11:11**MOT test number** 495530871235**Result** ✓ Passed



MOT #4	2010-09-09 11:49
MOT test number	220122150269
Result	✓ Passed
MOT #3	2009-09-21 13:36
MOT test number	404844969266
Result	✓ Passed
MOT #2	2008-09-22 11:34
MOT test number	773506068262
Result	✓ Passed
MOT #1	2007-09-24 10:35
MOT test number	420357467204
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
15 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	15 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-09-29
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2004-09-29	23 mi
Registration #2	2007-09-24	7.485 mi
Registration #3	2008-09-22	8.690 mi
Registration #4	2009-09-21	9.594 mi
Registration #5	2010-09-09	11.090 mi
Registration #6	2011-09-27	12.446 mi
Registration #7	2012-09-26	12.477 mi
Registration #8	2012-09-28	12.487 mi
Registration #9	2013-09-18	13.232 mi
Registration #10	2013-09-24	13.273 mi
Registration #11	2014-09-26	14.533 mi
Registration #12	2015-09-24	15.204 mi
Registration #13	2016-09-13	15.601 mi
Registration #14	2016-09-20	15.601 mi
Registration #15	2016-09-20	15.601 mi
Registration #16	2016-09-20	15.601 mi
Registration #17	2016-09-20	15.601 mi
Registration #18	2016-09-20	15.601 mi
Registration #19	2016-09-20	15.601 mi
Registration #20	2016-09-20	15.601 mi
Registration #21	2016-09-20	15.601 mi
Registration #22	2016-09-20	15.601 mi
Registration #23	2016-09-20	15.601 mi
Registration #24	2016-09-20	15.601 mi
Registration #25	2016-09-20	15.601 mi
Registration #26	2024-04-16	15.601 mi

**More info** >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	476785357FB