



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D





MOT history

MOT expiry date	2024-11-21
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	14
Total items failed	7

MOT #18 2023-11-21 10:39

MOT test number 984036485900

Result ✓ Passed

Next expiry date 2024-11-21

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #17 2023-11-21 10:39

MOT test number 732530624990

Result ✗ Failed

- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Road wheel fixing missing all wheels (5.2.1 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust mounting defective (6.1.2 (a))

**MOT #16** 2022-11-07 10:21**MOT test number** 827227396981**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2021-11-22 14:09**MOT test number** 121543719261**Result** ✓ Passed**MOT #14** 2021-11-22 14:09**MOT test number** 242428953982**Result** ✗ Failed**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #13** 2020-11-09 16:26**MOT test number** 551037051557**Result** ✓ Passed**MOT #12** 2019-04-26 13:26**MOT test number** 992315112450**Result** ✓ Passed**MOT #11** 2019-04-25 12:17**MOT test number** 722055290727**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #10** 2018-05-01 11:40**MOT test number** 364497183841**Result** ✓ Passed**MOT #9** 2018-04-30 16:17**MOT test number** 655238675416**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #8** 2017-05-02 11:27**MOT test number** 956291250274**Result** ✓ Passed**MOT #7** 2016-05-03 16:09**MOT test number** 973987242003**Result** ✓ Passed**MOT #6** 2016-05-03 15:18**MOT test number** 359162525073**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2015-11-02 11:10**MOT test number** 963366432950**Result** ✓ Passed



MOT #4	2015-11-02 11:10
MOT test number	576999816602
Result	✗ Failed
<div>Pass with rectification</div> Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #3	2014-11-06 09:37
MOT test number	596280114301
Result	✓ Passed

MOT #2	2013-10-14 10:36
MOT test number	768767483240
Result	✓ Passed

MOT #1	2012-10-05 14:26
MOT test number	836929772247
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
21 November 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SL59YBB
Plate since	2019-06-29
Current registration	 SL59YBB
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-10-15
Last registration	2023-11-21
Complete history	See info



Registration #1	2009-10-15	27 mi
Registration #2	2012-10-05	9.514 mi
Registration #3	2013-10-14	13.201 mi
Registration #4	2014-11-06	18.991 mi
Registration #5	2015-11-02	24.648 mi
Registration #6	2015-11-02	24.648 mi
Registration #7	2016-05-03	26.929 mi
Registration #8	2016-05-03	26.929 mi
Registration #9	2017-05-02	48.325 mi
Registration #10	2018-04-30	60.897 mi
Registration #11	2019-05-02	73.377 mi
Registration #12	2019-05-02	73.377 mi
Registration #13	2019-05-02	73.377 mi
Registration #14	2019-05-02	73.377 mi
Registration #15	2019-05-02	73.377 mi
Registration #16	2019-05-02	73.377 mi
Registration #17	2019-05-02	73.377 mi
Registration #18	2019-05-02	73.377 mi
Registration #19	2019-05-02	73.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBD 106784