



report date: 2024-03-28

## General information

Make	VOLVO
Model	C30 D5 SE LUX
Colour	Black
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	180 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	182 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-05-18
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	17
Total items failed	2

## MOT #14 2023-05-19 15:18

MOT test number 621880497322

Result ✓ Passed

Next expiry date 2024-05-18

- Advice** Sill covers fitted
- Advice** Engine cover fitted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Under tray fitted

## MOT #13 2022-02-26 08:29

MOT test number 202686612960

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #12 2021-03-16 16:08

MOT test number 773577664392

Result ✓ Passed

## MOT #11 2020-04-29 12:50

MOT test number 713104406884

Result ✓ Passed

**MOT #10** 2019-06-08 09:37**MOT test number** 358575029075**Result** ✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge recommend replacement (5.2.3 (e))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2018-06-07 13:02**MOT test number** 852939936682**Result** ✓ Passed**MOT #8** 2017-06-12 15:09**MOT test number** 458095603743**Result** ✓ Passed

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2016-05-23 11:06**MOT test number** 453239347934**Result** ✓ Passed

**Advice** Handbrake travel nearly to excess

**MOT #6** 2015-05-06 15:24**MOT test number** 496586325189**Result** ✓ Passed

**Notice** N/s/r tyre 2mm

**MOT #5** 2014-04-15 12:22**MOT test number** 328645204141**Result** ✓ Passed**MOT #4** 2014-04-14 10:26**MOT test number** 206504304114**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Exhaust particulate filter missing where one was fitted as standard (7.1.3)**MOT #3** 2013-06-27 10:00**MOT test number** 528008473119**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/f tyre wearing on outer edge**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Both front tyres wearing on inner edges**MOT #2** 2012-07-27 10:18**MOT test number** 369189202266**Result** ✓ Passed**MOT #1** 2011-11-26 09:32**MOT test number** 819650031348**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
2 February 2024

✓

MOT

Expires:  
18 May 2024

Tax status	Expired at 2 February 2024
Days left	86 days too late
MOT expiry date	18 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-12-24
Last registration	2023-05-19
Complete history	<a href="#">See info</a>



Registration #1	2008-12-24	8 mi
Registration #2	2011-11-26	25.218 mi
Registration #3	2012-07-27	27.452 mi
Registration #4	2013-06-27	32.308 mi
Registration #5	2014-04-14	36.070 mi
Registration #6	2014-04-15	36.072 mi
Registration #7	2015-05-06	57.399 mi
Registration #8	2016-05-23	74.050 mi
Registration #9	2016-05-23	74.050 mi
Registration #10	2016-05-23	74.050 mi
Registration #11	2016-05-23	74.050 mi
Registration #12	2016-05-23	74.050 mi
Registration #13	2016-05-23	74.050 mi
Registration #14	2016-05-23	74.050 mi
Registration #15	2016-05-23	74.050 mi
Registration #16	2016-05-23	74.050 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1490 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	586786