





report date: 2024-03-29

General information

Make	BMW
Model	316 520D SE
Colour	Blue
Year of manufacture	2016
Top speed	145 mph
0 - 60 mph	7.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2022-03-01

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-02-22
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	8

MOT #6	2024-02-23 14:33
MOT test number	826850399000
Result	✓ Passed
Next expiry date	2025-02-22

MOT #5	2024-02-22 11:54
MOT test number	524279504895
Result	★ Failed
Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously	weakened (1.1.14 (a) (ii))
Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))	
Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Minor Brake fluid warning lamp illuminated (1.1.10 (f))	
Fail Nearside Front Hydraulic brake calliper inadequately mounted (1.1.16	5 (c) (i))
Advice Offside Front Brake disc worn, pitted or scored, but not seriously w	veakened (1.1.14 (a) (ii))
Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a)	(i))

CarCheck.co.uk page 3/11



MOT #4 2022-11-25 10:23

MOT test number 630040427668

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3 2021-09-20 08:45

MOT test number 932603594517

Result \rightarrow Passed

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #2 2020-09-25 09:36

MOT test number 905636867563

Result Passed

Minor Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2019-10-10 09:46

MOT test number 289027614841

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1

Date

Category Type

Damage 2

Date

Category

Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners di	
Check it in the premium report and see all owner registrations. Download the full report h	<u>lere</u> .

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Europeat regulatration	NE UK
	UK
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 9/11



OY66WKA

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-10-18
Last registration	2024-02-23
Complete history	See info



Registration #1	2016-10-18	26 mi
Registration #2	2019-10-10	37.755 mi
Registration #3	2020-09-25	47.094 mi
Registration #4	2021-09-20	54.353 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1475 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1630 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 73209539