




report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Black
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K



**MOT history**

<b>MOT expiry date</b>	2025-01-07
<b>MOT pass rate</b>	61 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	7
<b>Total advice items</b>	24
<b>Total items failed</b>	19

<b>MOT #18</b>	2024-01-08 13:44
<b>MOT test number</b>	133710457911
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-07
<b>Advice</b>	Offside Play in steering rack inner joint(s)

<b>MOT #17</b>	2024-01-04 15:45
<b>MOT test number</b>	463517310332
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Play in steering rack inner joint(s)
<b>Fail</b>	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>Fail</b>	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
<b>Fail</b>	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

<b>MOT #16</b>	2022-12-05 15:00
<b>MOT test number</b>	475000711988
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #15** 2021-11-30 08:13**MOT test number** 843081826228**Result** ✓ Passed**MOT #14** 2021-11-29 14:47**MOT test number** 254886111363**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #13** 2020-10-19 13:16**MOT test number** 969647280045**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing outer edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))**MOT #12** 2020-10-19 10:15**MOT test number** 922137829834**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing outer edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2020-09-30 10:32**MOT test number** 603251297081**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #10** 2019-10-15 10:42**MOT test number** 251121882660**Result** ✓ Passed**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated Cut but preventing the ingress of dirt (5.3.4 (b) (i))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt Both sides**Advice** Rear Tyre slightly damaged/cracking or perishing Both sides, side walls perishing (5.2.3 (d) (ii))**MOT #9** 2018-10-17 11:34**MOT test number** 410809637545**Result** ✓ Passed

**MOT #8** 2018-10-15 16:18**MOT test number** 391297673900**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Fail** Front Windscreen washer not working both (3.5 (a))**MOT #7** 2018-01-05 15:08**MOT test number** 325961152390**Result** ✓ Passed**MOT #6** 2018-01-05 13:01**MOT test number** 656033451553**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Fail** Nearside Rear Wheel bolt(s) missing (4.2.A.1e)**MOT #5** 2017-01-06 12:43**MOT test number** 367794403438**Result** ✓ Passed

**MOT #4** 2017-01-05 12:15**MOT test number** 478806960460**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Central Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-01-06 11:25**MOT test number** 903318239347**Result** ✓ Passed**MOT #2** 2015-01-27 09:37**MOT test number** 506477925056**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-02-14 13:37**MOT test number** 738425144066**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
7 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	7 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 <b>AF11VUH</b>
Plate since	2019-09-28
Current registration	 <b>AF11VUH</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-03-15
Last registration	2024-01-08
Complete history	<a href="#">See info</a>



Registration #1	2011-03-15	28 mi
Registration #2	2014-02-14	32.822 mi
Registration #3	2015-01-27	43.914 mi
Registration #4	2016-01-06	56.831 mi
Registration #5	2017-01-05	72.756 mi
Registration #6	2017-01-06	72.756 mi
Registration #7	2018-01-05	80.735 mi
Registration #8	2018-01-05	80.735 mi
Registration #9	2018-10-15	83.897 mi
Registration #10	2018-10-17	83.897 mi
Registration #11	2019-01-01	85.000 mi
Registration #12	2019-01-01	85.000 mi
Registration #13	2019-01-01	85.000 mi
Registration #14	2019-01-01	85.000 mi
Registration #15	2019-01-01	85.000 mi
Registration #16	2019-01-01	85.000 mi
Registration #17	2019-01-01	85.000 mi
Registration #18	2019-01-01	85.000 mi
Registration #19	2019-01-01	85.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	1044305