



SLIOEWA

report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI E SE
Colour	White
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-05-26
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-09
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	42
Total items failed	9

MOT #17	2023-06-05 09:16
MOT test number	226259738389
Result	✓ Passed
Next expiry date	2024-06-09
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #16	2022-06-06 11:25
MOT test number	618076764173
Result	✓ Passed

MOT #15	2022-06-06 11:25
MOT test number	708513415891
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #14	2021-06-10 11:27
MOT test number	759654564351
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #13** 2021-05-26 15:34**MOT test number** 155086458439**Result** ✗ Failed**Fail** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central exhaust clamp insecure/broken**MOT #12** 2020-06-03 09:04**MOT test number** 125814014727**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-05-31 14:55**MOT test number** 494410289975**Result** ✓ Passed**MOT #10** 2019-05-31 14:55**MOT test number** 826961882954**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #9**

2018-05-30 11:51

MOT test number

120671926572

Result

✓ Passed

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Nail in tyre

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Side skirt plastic trim damaged

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8

2017-05-26 11:21

MOT test number

837421566657

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7

2016-05-31 11:33

MOT test number

389598073442

Result

✓ Passed

Advice Emissions too low to record

Advice Engine cover fitted also under trays



MOT #6 2015-05-26 12:36

MOT test number 255596845461

Result ✓ Passed

- Notice** Offside rear tyre tread is worn almost smooth on inner edge,possibly tracking?
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** All tyres treads are wearing on inner edges,possibly tracking?
- Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test

MOT #5 2015-05-26 12:36

MOT test number 259866445142

Result ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Notice** Offside rear tyre tread is worn almost smooth on inner edge,possibly tracking?
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** All tyres treads are wearing on inner edges,possibly tracking?
- Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2014-06-02 09:55**MOT test number** 497913354182**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2014-06-02 09:55**MOT test number** 258023454184**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2013-02-28 15:11**MOT test number** 896389553064**Result** ✓ Passed**MOT #1** 2013-02-28 12:05**MOT test number** 588499153077**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
9 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-22
Last registration	2023-06-05
Complete history	See info



Registration #1	2010-03-22	22 mi
Registration #2	2013-02-28	56.489 mi
Registration #3	2013-02-28	56.489 mi
Registration #4	2014-06-02	82.111 mi
Registration #5	2015-05-26	90.658 mi
Registration #6	2016-05-31	99.359 mi
Registration #7	2017-05-26	107.104 mi
Registration #8	2018-05-30	115.554 mi
Registration #9	2019-05-31	124.846 mi
Registration #10	2020-05-31	134.138 mi
Registration #11	2021-05-31	143.430 mi
Registration #12	2022-05-31	152.722 mi
Registration #13	2023-05-31	162.014 mi
Registration #14	2024-05-31	171.306 mi
Registration #15	2025-05-31	180.598 mi
Registration #16	2026-05-31	189.890 mi
Registration #17	2027-05-31	199.182 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1475 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CAG 347957