



report date: 2024-03-28

General information

Make	MAZDA
Model	3 TAKARA
Colour	Blue
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	103 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-16
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-27
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	44
Total items failed	9

MOT #17 2024-04-25 15:39

MOT test number 681163522002

Result ✓ Passed

Next expiry date 2025-04-27

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))
- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #16 2024-04-25 13:43

MOT test number 741968388312

Result ✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Front Headlamp not working on main beam Both (4.1.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))
- Fail** Brake fluid contaminated (1.8 (a))

**MOT #15**

2023-04-28 16:57

**MOT test number**

283474667416

**Result**

✓ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both side. (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin both side. (1.1.13 (a) (ii))

**MOT #14**

2022-04-19 15:00

**MOT test number**

502452458531

**Result**

✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #13**

2021-04-28 12:04

**MOT test number**

790520874769

**Result**

✓ Passed

- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened and offside (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-06-20 09:57**MOT test number** 143699191041**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-06-14 15:35**MOT test number** 740072051936**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2018-06-12 14:17**MOT test number** 591713242534**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Brake hose leaking on a hydraulic braking system (1.1.12 (c) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #9** 2017-04-05 15:16**MOT test number** 895181918354**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8**

2017-04-05 09:01

**MOT test number**

254442304994

**Result****✗ Failed****Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail**

Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice**

Front Brake pad(s) wearing thin (3.5.1g)

**Advice**

Offside Rear tyre sidewall cracking

**Fail**

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7**

2016-03-31 09:47

**MOT test number**

550256553455

**Result****✓ Passed****Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Nearside Rear tyre punctured and starting to crack

**Advice**

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2016-03-29 14:11

**MOT test number**

437679950697

**Result****✗ Failed****Fail**

Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Nearside Rear tyre punctured and starting to crack

**Advice**

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-03-11 12:37**MOT test number** 778370475033**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2014-03-26 16:38**MOT test number** 597225584065**Result** ✓ Passed**MOT #3** 2013-04-26 09:43**MOT test number** 227136713114**Result** ✓ Passed**MOT #2** 2012-04-19 12:16**MOT test number** 816560112149**Result** ✓ Passed**MOT #1** 2011-04-19 12:06**MOT test number** 946339401122**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
27 April 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	27 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-30
Last registration	2024-04-25
Complete history	<a href="#">See info</a>



Registration #1	2008-04-30	17 mi
Registration #2	2011-04-19	14.814 mi
Registration #3	2012-04-19	21.991 mi
Registration #4	2013-04-26	28.419 mi
Registration #5	2014-03-26	34.273 mi
Registration #6	2015-03-11	39.203 mi
Registration #7	2016-03-29	43.629 mi
Registration #8	2016-03-31	43.629 mi
Registration #9	2017-04-05	48.056 mi
Registration #10	2017-04-05	48.056 mi
Registration #11	2018-04-05	52.482 mi
Registration #12	2019-04-05	56.908 mi
Registration #13	2020-04-05	61.334 mi
Registration #14	2021-04-05	65.760 mi
Registration #15	2022-04-05	70.186 mi
Registration #16	2023-04-05	74.612 mi
Registration #17	2024-04-05	79.038 mi
Registration #18	2024-04-25	83.464 mi
Registration #19	2024-04-25	87.890 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4440 mm
Wheel base	2640 mm
Kerb weight	1290 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	Z6 717071