



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	137 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-06-03
Pictures	30
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-27
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #12	2023-05-17 15:23
MOT test number	910663307056
Result	✓ Passed
Next expiry date	2024-05-27
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-05-28 08:12
MOT test number	869635886643
Result	✓ Passed

MOT #10	2021-06-29 13:01
MOT test number	122321512751
Result	✓ Passed

MOT #9	2021-06-29 09:03
MOT test number	747645055137
Result	✗ Failed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2020-07-22 10:14**MOT test number** 431908645112**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-07-01 10:09**MOT test number** 847273579374**Result** ✓ Passed**MOT #6** 2018-07-30 15:10**MOT test number** 714710859769**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #5** 2017-07-17 08:47**MOT test number** 518432499236**Result** ✓ Passed**Advice** Both rear tyres slightly cracked**MOT #4** 2017-07-17 08:47**MOT test number** 362248180110**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Both rear tyres slightly cracked**MOT #3** 2016-07-11 09:05**MOT test number** 800436283651**Result** ✓ Passed



MOT #2	2015-07-30 10:27
MOT test number	271757876185
Result	✓ Passed
MOT #1	2014-10-13 12:56
MOT test number	935616284275
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
27 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	27 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LD61YUG
Plate since	2024-03-29
Current registration	LD61YUG
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-10-18
Last registration	2023-05-17
Complete history	See info



Registration #1	2011-10-18	15 mi
Registration #2	2014-10-13	25.308 mi
Registration #3	2015-07-30	30.360 mi
Registration #4	2016-07-11	35.299 mi
Registration #5	2017-07-17	42.456 mi
Registration #6	2017-07-17	42.456 mi
Registration #7	2018-07-30	48.519 mi
Registration #8	2019-05-20	55.577 mi
Registration #9	2019-05-20	55.577 mi
Registration #10	2019-05-20	55.577 mi
Registration #11	2019-05-20	55.577 mi
Registration #12	2019-05-20	55.577 mi
Registration #13	2019-05-20	55.577 mi
Registration #14	2019-05-20	55.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1785 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1007260