



CITROËN



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA PICASSO LX
Colour	Purple
Year of manufacture	2002
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	135 Nm at 3.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-11-05
Pictures	25
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-10-01
Pictures	25
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-12-30
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	39
Total items failed	9

MOT #22	2020-12-07 11:47
---------	------------------

MOT test number	738900206155
-----------------	--------------

Result	✓ Passed
Next expiry date	2021-12-30
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view wiper damage (3.2 (a) (i))
Advice	Nearside Seat belt anchorage prescribed area is corroded but not considered excessive outer body sill damaged (7.1.1 (a) (i))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Clutch pedal anti slip rubber missing
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Items removed from driver's view prior to test
Advice	Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

**MOT #21** 2019-07-01 13:01**MOT test number** 460881702950**Result** ✓ Passed**Advice** Rear exhaust corroded and knocking on bumper**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Windscreen damaged but not adversely affecting driver's view scratches to n/s (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #20** 2019-07-01 09:14**MOT test number** 288515375068**Result** ✗ Failed**MAJOR** Nearside Windscreen washer not working (3.5 (a))**Minor** Windscreen damaged but not adversely affecting driver's view scratches to n/s (3.2 (a) (i))**Advice** Offside Front Nail in tyre**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Rear exhaust corroded and knocking on bumper**MAJOR** Offside Windscreen washer not working (3.5 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #19** 2018-06-26 13:51**MOT test number** 407209038465**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18** 2018-06-26 09:00**MOT test number** 598334158956**Result** ✗ Failed**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Side repeater incorrect colour (4.4.3 (a))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Side repeater incorrect colour (4.4.3 (a))**MOT #17** 2017-06-19 10:09**MOT test number** 737292892654**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #16** 2016-06-17 10:05**MOT test number** 808541810571**Result** ✓ Passed**MOT #15** 2015-06-19 15:27**MOT test number** 585760775158**Result** ✓ Passed

**MOT #14** 2015-06-19 10:09**MOT test number** 788860175105**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #13** 2014-06-06 12:19**MOT test number** 718767854164**Result** ✓ Passed**MOT #12** 2014-06-06 12:19**MOT test number** 698437854145**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #11** 2013-06-18 11:34**MOT test number** 619569563170**Result** ✓ Passed**MOT #10** 2013-06-18 11:34**MOT test number** 538969863148**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #9** 2012-06-26 16:16**MOT test number** 829238772114**Result** ✓ Passed



MOT #8	2012-06-22 13:10
---------------	------------------

MOT test number	608604272184
------------------------	--------------

Result	✗ Failed
---------------	----------

- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2011-06-21 11:39
---------------	------------------

MOT test number	407512171185
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2010-06-09 13:26
---------------	------------------

MOT test number	262750960449
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2009-06-02 12:04
---------------	------------------

MOT test number	660173359132
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2008-06-10 13:25
---------------	------------------

MOT test number	451182868148
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #3** 2007-09-13 09:29**MOT test number** 362876957494**Result** ✗ Failed**Pass with rectification** Rear Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #2** 2007-09-13 09:29**MOT test number** 800166257281**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #1** 2006-05-31 13:17**MOT test number** 232171056173**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front Brake lining(s) wearing thin (3.5.1g)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-05-07
Last registration	2020-12-07
Complete history	See info



Registration #1	2002-05-07	18 mi
Registration #2	2006-05-31	22.967 mi
Registration #3	2007-09-13	32.903 mi
Registration #4	2008-06-10	38.715 mi
Registration #5	2009-06-02	43.791 mi
Registration #6	2010-06-09	51.799 mi
Registration #7	2011-06-21	57.633 mi
Registration #8	2012-06-22	62.700 mi
Registration #9	2012-06-26	62.732 mi
Registration #10	2013-06-18	66.811 mi
Registration #11	2014-06-06	70.626 mi
Registration #12	2015-06-06	75.000 mi
Registration #13	2016-06-06	79.375 mi
Registration #14	2017-06-06	83.750 mi
Registration #15	2018-06-06	88.125 mi
Registration #16	2019-06-06	92.500 mi
Registration #17	2020-06-06	96.875 mi
Registration #18	2021-06-06	101.250 mi
Registration #19	2022-06-06	105.625 mi
Registration #20	2023-06-06	110.000 mi
Registration #21	2024-06-06	114.375 mi
Registration #22	2025-06-06	118.750 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1752 mm
Height	1625 mm
Length	4267 mm
Wheel base	2760 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	FX3F1441636