





General information

Make	HYUNDAI
Model	VELOSTER GDI
Colour	Silver
Year of manufacture	2012
Top speed	125 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	137 BHP
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F







Internet history

Entry 1	
Date	202
Pictures	12

21-10-08

12

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #12	2023-07-19 10:58
MOT test number	594877156086
Result	✓ Passed
Next expiry date	2024-08-15
Advice Front Tyre slightly damaged n/s and o/s (5.2.3 (d) (ii))	

MOT #11		2022-07-18 13:52
MOT test	number	499809175624
Result		✓ Passed
Advice	Front Tyre slightly damaged n/s and o/s (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))	

MOT #10 20	022-07-18 11:03
MOT test number	913368450883
Result	🗙 Failed
Advice Front Tyre slightly damaged n/s and o/s (5.2.3 (d) (ii))	
Fail Offside Rear Service brake lagging in operation (1.2.1 (d))	
Advice Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	





MOT #9	2021-08-16 15:34
MOT test number	233579923434
Result	✓ Passed
MOT #8	2020-11-23 16:06
MOT test number	528856460653
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MOT #7	2019-11-22 13:29
MOT test number	552542590913
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))
MOT #6	2018-11-24 12:14
MOT test number	873658411865
Result	✓ Passed
MOT #5	2017-11-24 10:35
MOT test number	378316124399
Result	✓ Passed
MOT #4	2017-10-03 08:03
MOT test number	167800404431
Result	Description
	✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)





MOT #3		2017-10-03 08:03
MOT test number		603552481509
Result		🗙 Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	
Advice Under trays fitted		
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Parking brake lever has little reserve travel (3.1.6b)		

MOT #2		2016-09-22 12:04
MOT test	number	764363696879
Result		✓ Passed
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
Advice	Parking brake efficiency 20% - this only just met the requirements	

MOT #1	2015-09-07 12:48
MOT test number	309716637165
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	MOT Expires: 15 August 2024
Tax status	Valid until 1 October
Days left	154
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lashe
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	 *
Category	 amer
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF CONTRACTOR OF CONTRA	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-28
Last registration	2023-07-19
Complete history	See info



Registration #1	2012-09-28	26 mi
Registration #2	2015-09-07	42.608 mi
Registration #3	2016-09-22	63.789 mi
Registration #4	2017-10-03	87.107 mi
Registration #5	2017-10-03	87.107 mi
Registration #6	2017-11-24	87.280 mi
Registration #7	2018-11-24	92.644 mi
Registration #8		11.777 esi
Registration #8 Registration #9		11.517 est 11.517 est
-		10.000 est 00.000 est 00.000 est
Registration #9		0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg
Additional information	
Fuel tank capacity	50
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	4 page 12/12