



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Silver
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-07-23
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-01
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-20
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	38
Total items failed	11

MOT #20	2024-03-21 10:17
MOT test number	808447061392
Result	✓ Passed
Next expiry date	2025-03-20
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #19	2023-05-31 16:15
MOT test number	237509098139
Result	✓ Passed
Advice	Exhaust silencer outer casing loose
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #18**

2023-05-31 11:51

MOT test number

411279005801

Result**✗ Failed****Fail**

Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail

Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Exhaust silencer outer casing loose

Fail

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #17

2022-06-10 08:06

MOT test number

848686307385

Result**✓ Passed****MOT #16**

2021-05-26 08:02

MOT test number

118466686695

Result**✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge Worn on edges (5.2.3 (e))

**MOT #15**

2020-06-10 12:20

MOT test number

513813518142

Result

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Drive belt worn, but not excessively (6.1.7 (c) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2020-06-09 15:09

MOT test number

564962667690

Result

✗ Failed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Drive belt worn, but not excessively (6.1.7 (c) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-04-16 09:50**MOT test number** 472986519759**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-04-11 13:39**MOT test number** 102151616887**Result** ✓ Passed**Advice** Offside rear tyre inner side wall perished**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2018-04-11 09:54**MOT test number** 952023365722**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Braking system leaking (3.6.A.1)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)**Advice** Offside rear tyre inner side wall perished**Fail** Nearside rear brake recording little or no effort (3.7.B.5a)

**MOT #10** 2017-04-11 08:09**MOT test number** 156960355651**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** O/s/r tyre perishing**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-04-29 07:17**MOT test number** 884802220983**Result** ✓ Passed**MOT #8** 2015-05-01 15:20**MOT test number** 899001025127**Result** ✓ Passed**Notice** Rear exhaust bracket slight worn**MOT #7** 2014-05-02 07:16**MOT test number** 497252824119**Result** ✓ Passed**Notice** N/s/f tyre wearing outer edge**MOT #6** 2013-04-25 14:26**MOT test number** 619595113156**Result** ✓ Passed**MOT #5** 2012-05-05 11:47**MOT test number** 519896422138**Result** ✓ Passed**Notice** Nearside rear tyre perished and on 2-3mm tread.

**MOT #4** 2011-04-30 13:50**MOT test number** 435620221140**Result** ✓ Passed**MOT #3** 2011-04-30 12:43**MOT test number** 929470521151**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2010-05-01 13:03**MOT test number** 104101020115**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-05-02 13:38**MOT test number** 914512129196**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-05-05
Last registration	2024-03-21
Complete history	See info



Registration #1	2006-05-05	27 mi
Registration #2	2009-05-02	23.189 mi
Registration #3	2010-05-01	27.336 mi
Registration #4	2011-04-30	30.564 mi
Registration #5	2011-04-30	30.564 mi
Registration #6	2012-05-05	32.965 mi
Registration #7	2013-04-25	35.289 mi
Registration #8	2014-05-02	39.083 mi
Registration #9	2015-05-01	43.171 mi
Registration #10	2016-04-29	46.815 mi
Registration #11	2017-04-11	49.634 mi
Registration #12	2018-04-11	52.918 mi
Registration #13	2019-05-01	55.377 mi
Registration #14	2020-05-01	57.917 mi
Registration #15	2021-05-01	60.537 mi
Registration #16	2022-05-01	63.237 mi
Registration #17	2023-05-01	66.017 mi
Registration #18	2024-03-21	68.877 mi
Registration #19	2024-03-21	68.877 mi
Registration #20	2024-03-21	68.877 mi
Registration #21	2024-03-21	68.877 mi
Registration #22	2024-03-21	68.877 mi
Registration #23	2024-03-21	68.877 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3097262