



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Grey
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-09-22
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-20
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	31
Total items failed	0

MOT #15	2023-08-02 10:50
MOT test number	247859572393
Result	✓ Passed
Next expiry date	2024-08-08
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing starting to perish (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing starting to perish (5.2.3 (d) (ii))

MOT #14	2022-08-09 12:55
MOT test number	969838948110
Result	✓ Passed

MOT #13	2021-10-19 12:53
MOT test number	470638467571
Result	✓ Passed



MOT #12	2021-10-18 15:07
MOT test number	851045639715
Result	✗ Failed
MAJOR	Offside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
MAJOR	Nearside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #11	2021-02-08 11:09
MOT test number	604735437816
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #10	2020-02-13 15:17
MOT test number	461763079894
Result	✓ Passed
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm bushes (5.3.4 (a) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #9** 2020-02-13 11:59**MOT test number** 551289972260**Result** ✗ Failed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm bushes (5.3.4 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #8** 2019-01-25 14:22**MOT test number** 289996874590**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-01-23 14:21**MOT test number** 893987703200**Result** ✗ Failed**MAJOR** Offside Front Steering arm modification unsafe (2.1.3 (f) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-02-17 12:30**MOT test number** 917411278167**Result** ✓ Passed

**MOT #5** 2017-03-20 13:01**MOT test number** 299339597882**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-03-16 15:43**MOT test number** 199268924628**Result** ✓ Passed**Advice** Botn inner steering rack joints have play**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-03-19 11:35**MOT test number** 267918675098**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Both front wiper blades smeary**MOT #2** 2014-03-20 12:06**MOT test number** 578019774042**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)



MOT #1	2013-03-18 16:14
MOT test number	739457173053
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
8 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	8 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-23
Last registration	2023-08-02
Complete history	<a href="#">See info</a>



Registration #1	2010-03-23	10 mi
Registration #2	2013-03-18	25.805 mi
Registration #3	2014-03-20	34.099 mi
Registration #4	2015-03-19	41.939 mi
Registration #5	2016-03-16	48.877 mi
Registration #6	2017-03-20	55.635 mi
Registration #7	2018-02-17	59.930 mi
Registration #8	2019-01-23	68.929 mi
Registration #9	2019-01-25	68.946 mi
Registration #10	2019-01-25	68.946 mi
Registration #11	2019-01-25	68.946 mi
Registration #12	2019-01-25	68.946 mi
Registration #13	2019-01-25	68.946 mi
Registration #14	2019-01-25	68.946 mi
Registration #15	2019-01-25	68.946 mi
Registration #16	2019-01-25	68.946 mi
Registration #17	2019-01-25	68.946 mi
Registration #18	2019-01-25	68.946 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	672615
---------------	--------