



RV56EXW

report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SPORT
Colour	Blue
Year of manufacture	2006
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	331 Nm at 1.800 rpm
Engine capacity	1.988 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





MOT history

MOT expiry date	2025-02-19
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	33
Total items failed	2

MOT #17	2024-02-20 09:04
MOT test number	609671725164
Result	✓ Passed
Next expiry date	2025-02-19
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #16	2024-02-02 17:06
MOT test number	333619745120
Result	✗ Failed
DANGEROUS	Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm BOTH (5.2.3 (e))
MAJOR	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
DANGEROUS	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MOT #15	2023-01-31 13:17
MOT test number	660272381094
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))

**MOT #14** 2021-10-20 12:56**MOT test number** 936100454763**Result** ✓ Passed**MOT #13** 2020-10-13 08:00**MOT test number** 753478457150**Result** ✓ Passed**MOT #12** 2019-10-14 08:22**MOT test number** 553304857246**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on the inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and worn on the inner edge (5.2.3 (e))**MOT #11** 2018-10-03 08:56**MOT test number** 669697774838**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2017-10-17 09:44**MOT test number** 437256364187**Result** ✓ Passed**Advice** Nearside Front tyre worn on the edges**Advice** Central Brake pipe slightly corroded (3.6.B.2c)

**MOT #9** 2017-10-12 10:01**MOT test number** 323252075658**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front tyre worn on the edges**Advice** Central Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #8** 2016-09-26 08:37**MOT test number** 884277542944**Result** ✓ Passed**MOT #7** 2015-09-23 08:35**MOT test number** 963236092763**Result** ✓ Passed**MOT #6** 2014-10-13 12:43**MOT test number** 145546984273**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Under-trays fitted obscuring some underside components

**MOT #5**

2013-09-18 09:33

MOT test number

368151063276

Result

✓ Passed

- Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Both rear tyres cracked/perished on inner sidewalls
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Both front wiper blades deteriorated
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #4

2012-09-14 14:54

MOT test number

156908352269

Result

✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

2011-09-10 10:17

MOT test number

479583851280

Result

✓ Passed



MOT #2	2010-08-27 10:32
MOT test number	901519230224
Result	✓ Passed
MOT #1	2009-08-21 12:11
MOT test number	351053439276
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
19 February 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	19 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-20
Last registration	2024-02-20
Complete history	See info



Registration #1	2006-09-20	12 mi
Registration #2	2009-08-21	53.798 mi
Registration #3	2010-08-27	68.337 mi
Registration #4	2011-09-10	76.082 mi
Registration #5	2012-09-14	83.443 mi
Registration #6	2013-09-18	87.425 mi
Registration #7	2014-10-13	91.607 mi
Registration #8	2015-09-23	96.303 mi
Registration #9	2016-09-26	100.573 mi
Registration #10	2017-09-26	104.848 mi
Registration #11	2018-09-26	109.123 mi
Registration #12	2019-09-26	113.398 mi
Registration #13	2020-09-26	117.673 mi
Registration #14	2021-09-26	121.948 mi
Registration #15	2022-09-26	126.223 mi
Registration #16	2023-09-26	130.498 mi
Registration #17	2024-02-20	134.773 mi
Registration #18	2024-02-20	139.048 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1575 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0605151658106G