



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRTD CDX
Colour	Black
Year of manufacture	2006
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	335 Nm at 1.800 rpm
Engine capacity	2.188 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.0 mpg
CO2 emission	220 g/km
CO2 label	K





MOT history

MOT expiry date	2021-03-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	5

MOT #16	2020-03-17 15:36
MOT test number	698264565872
Result	✓ Passed
Next expiry date	2021-03-16
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2019-03-16 11:26
MOT test number	895841435346
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14	2018-03-07 08:57
MOT test number	321193731215
Result	✓ Passed
Advice	Brake pad(s) wearing thin both sides front (3.5.1g)
Advice	Tyre worn close to the legal limit both sides front (4.1.E.1)



MOT #13	2018-03-06 09:27
MOT test number	722370162246
Result	✗ Failed
Fail	Nearside Front Lower Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #12	2017-03-11 09:59
MOT test number	981394691101
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Brake pad(s) wearing thin both front and rear (3.5.1g)
Advice	Oil leak
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11	2016-03-12 10:35
MOT test number	579657546640
Result	✓ Passed
Advice	Brake pad(s) wearing thin both rear (3.5.1g)

MOT #10	2016-03-12 10:35
MOT test number	302512958032
Result	✗ Failed
Pass with rectification	Stop lamp not working both rear (1.2.1b)
Advice	Brake pad(s) wearing thin both rear (3.5.1g)

MOT #9	2015-03-17 09:53
MOT test number	505986175064
Result	✓ Passed

**MOT #8** 2014-03-06 16:56**MOT test number** 386145564015**Result** ✓ Passed**MOT #7** 2014-03-06 16:56**MOT test number** 375135964016**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2013-03-05 15:45**MOT test number** 857614163063**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2012-02-24 12:58**MOT test number** 315225252050**Result** ✓ Passed**MOT #4** 2011-03-17 16:55**MOT test number** 829126371003**Result** ✓ Passed



MOT #3	2010-05-05 09:58
---------------	------------------

MOT test number	723535520176
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Advise rear seats in away position with covers over boot floor
---------------	--

MOT #2	2009-04-23 09:24
---------------	------------------

MOT test number	484453619132
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2009-04-23 09:24
---------------	------------------

MOT test number	213683919114
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Front Headlamp aim too low (1.8)
--------------------------------	--



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EJ06TNV
Plate since	2019-03-29
Current registration	EJ06TNV
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-04-28
Last registration	2020-03-17
Complete history	See info



Registration #1	2006-04-28	9 mi
Registration #2	2009-04-23	29.038 mi
Registration #3	2010-05-05	38.284 mi
Registration #4	2011-03-17	45.098 mi
Registration #5	2012-02-24	49.840 mi
Registration #6	2013-03-05	57.578 mi
Registration #7	2014-03-06	67.350 mi
Registration #8	2015-03-17	80.092 mi
Registration #9	2016-03-17	92.834 mi
Registration #10	2017-03-17	105.576 mi
Registration #11	2018-03-17	118.318 mi
Registration #12	2019-03-17	131.060 mi
Registration #13	2020-03-17	143.802 mi
Registration #14	2021-03-17	156.544 mi
Registration #15	2022-03-17	169.286 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1725 mm
Length	4650 mm
Wheel base	2700 mm
Kerb weight	1853 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4EB6936091