



YYIIEHH

report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) ONE
Colour	White
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-07-02
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-06
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	7

MOT #14	2023-07-05 14:36
MOT test number	464874297045
Result	✓ Passed
Next expiry date	2024-07-06
Advice	Nearside Front Tyre slightly damaged/cracking or perishing Cracking and perishing. Worn edges (5.2.3 (d) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing Cracking and perishing to both sides (5.2.3 (d) (ii))

MOT #13	2022-07-07 14:53
MOT test number	410684799822
Result	✓ Passed

MOT #12	2022-01-07 10:11
MOT test number	318373438051
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Oil leak, but not excessive slight oil leak (8.4.1 (a) (i))

**MOT #11** 2022-01-07 10:11**MOT test number** 362651190722**Result** ✗ Failed**Advice** Oil leak, but not excessive slight oil leak (8.4.1 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #10** 2020-07-29 12:20**MOT test number** 591398316935**Result** ✓ Passed**MOT #9** 2020-07-29 09:54**MOT test number** 538667939389**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #8** 2019-04-20 09:39**MOT test number** 657846531340**Result** ✓ Passed**MOT #7** 2018-03-24 12:37**MOT test number** 879846941819**Result** ✓ Passed

**MOT #6** 2018-03-24 11:00**MOT test number** 932223567593**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit and perishing in tread and sidewall (4.1.E.1)**Advice** Offside Rear Nail in tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-03-24 12:29**MOT test number** 692743187094**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 3 mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 3 mm (4.1.E.1)**Advice** Offside Rear unable to distinguish between normal undulations in the carcass, resulting from manufacturing, and lumps or bulges caused by structural deterioration.**Advice** Offside Front Tyre worn close to the legal limit 3 mm and signs of wearing more on edge (4.1.E.1)**MOT #4** 2017-03-24 09:52**MOT test number** 193014678821**Result** ✗ Failed**Fail** Offside Headlamp aim too high and too far to the right. (1.8)**Advice** Offside Rear unable to distinguish between normal undulations in the carcass, resulting from manufacturing, and lumps or bulges caused by structural deterioration.**Advice** Offside Front Tyre worn close to the legal limit 3 mm and signs of wearing more on edge (4.1.E.1)**Fail** Nearside Headlamp aim too high (1.8)**Advice** Nearside Front Tyre worn close to the legal limit 3 mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit 3 mm (4.1.E.1)



MOT #3	2016-03-29 15:03
MOT test number	751107983524
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear tyre cut on s/wall
Advice	Offside Rear Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2015-04-21 16:42
MOT test number	908991715122
Result	✓ Passed

MOT #1	2014-04-16 16:21
MOT test number	839276704134
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
6 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	6 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-20
Last registration	2023-07-05
Complete history	<a href="#">See info</a>



Registration #1	2011-04-20	26 mi
Registration #2	2014-04-16	27.090 mi
Registration #3	2015-04-21	34.978 mi
Registration #4	2016-03-29	38.951 mi
Registration #5	2017-03-24	41.256 mi
Registration #6	2017-03-24	41.256 mi
Registration #7	2018-03-24	42.805 mi
Registration #8	2018-03-24	42.805 mi
Registration #9	2019-03-29	45.377 mi
Registration #10	2019-03-29	45.377 mi
Registration #11	2019-03-29	45.377 mi
Registration #12	2019-03-29	45.377 mi
Registration #13	2019-03-29	45.377 mi
Registration #14	2019-03-29	45.377 mi
Registration #15	2019-03-29	45.377 mi
Registration #16	2019-03-29	45.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	A207I939