



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Silver
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 3

Date 2021-09-17

Pictures 7

Listing price [View report](#)



source: yesauto.com

Entry 2

Date 2021-09-17

Pictures 12

Listing price [View report](#)




source: cargurus.co.uk

Entry 1

Date 2021-09-15

Pictures 12

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	30
Total items failed	14

MOT #20	2023-07-03 11:51
MOT test number	878325330014
Result	✓ Passed
Next expiry date	2024-07-04

MOT #19	2023-07-03 08:29
MOT test number	504165020889
Result	✗ Failed
Fail	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #18	2022-07-05 14:57
MOT test number	375427560335
Result	✓ Passed
Advice	Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to separate (5.3.4 (a) (i))
Advice	Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to separate (5.3.4 (a) (i))

**MOT #17**

2022-07-05 10:54

MOT test number

116896298037

Result**✗ Failed****Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to separate (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to separate (5.3.4 (a) (i))**MOT #16**

2021-11-12 16:18

MOT test number

314178965855

Result**✓ Passed****MOT #15**

2021-07-21 15:23

MOT test number

751980862413

Result**✓ Passed****MOT #14**

2021-07-21 08:56

MOT test number

286992127851

Result**✗ Failed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #13** 2020-07-21 09:06**MOT test number** 614143143298**Result** ✓ Passed

Advice Nearside Rear Other passenger door catch deteriorated but the door can still be readily opened and closed NSR door fault with external handle /lock. (6.2.3 (c) (i))

MOT #12 2019-08-19 13:26**MOT test number** 958329300793**Result** ✓ Passed**MOT #11** 2018-08-30 12:41**MOT test number** 286849944279**Result** ✓ Passed**MOT #10** 2018-05-03 10:49**MOT test number** 849648839272**Result** ✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Emissions too clean to register

Advice Nearside Side repeater obscured but not more than 50% (1.4.A.2d)

MOT #9 2018-05-03 09:07**MOT test number** 956477101345**Result** ✗ Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Nearside Side repeater obscured but not more than 50% (1.4.A.2d)

Advice Emissions too clean to register

Fail Registration plate lamp not working (1.1.C.1d)



MOT #8	2017-05-09 12:29
MOT test number	966329188747
Result	✓ Passed
Advice	Emissions too clean to register

MOT #7	2017-05-08 11:16
MOT test number	622253815068
Result	✗ Failed
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Emissions too clean to register
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #6	2016-05-06 15:31
MOT test number	576476052914
Result	✓ Passed

MOT #5	2015-05-07 12:10
MOT test number	295197325148
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components

**MOT #4** 2014-04-22 16:22**MOT test number** 988192114186**Result** Passed**MOT #3** 2014-04-17 12:09**MOT test number** 287627504423**Result** Failed

- Notice** Nail in nearside front tyre
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Under-trays fitted obscuring some underside components

MOT #2 2013-04-18 14:15**MOT test number** 567898803181**Result** Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #1 2013-04-16 11:56**MOT test number** 738546703137**Result** Failed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Osf tyre worn close to cords on inner tread
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

X

Untaxed

Tax expired:
13 September 2023

✓

MOT

Expires:
4 July 2024

Tax status	Expired at 13 September
Days left	229 days too late
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2010-05-06
Last registration	2023-07-03
Complete history	See info



Registration #1	2010-05-06	15 mi
Registration #2	2013-04-16	36.770 mi
Registration #3	2013-04-18	36.772 mi
Registration #4	2014-04-17	48.095 mi
Registration #5	2014-04-22	48.116 mi
Registration #6	2015-05-07	59.726 mi
Registration #7	2016-05-06	73.129 mi
Registration #8	2017-05-08	85.655 mi
Registration #9	2017-05-09	85.655 mi
Registration #10	2018-05-03	95.340 mi
Registration #11	2018-05-03	95.340 mi
Registration #12	2018-08-30	98.235 mi
Registration #13	2019-05-09	101.277 mi
Registration #14	2019-05-09	101.277 mi
Registration #15	2019-05-09	101.277 mi
Registration #16	2019-05-09	101.277 mi
Registration #17	2019-05-09	101.277 mi
Registration #18	2019-05-09	101.277 mi
Registration #19	2019-05-09	101.277 mi
Registration #20	2019-05-09	101.277 mi
Registration #21	2019-05-09	101.277 mi
Registration #22	2019-05-09	101.277 mi
Registration #23	2019-05-09	101.277 mi
Registration #24	2019-05-09	101.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1885 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	814021