





report date: 2024-03-28

#### General information

Make	HONDA
Model	ACCORD CTDI EX
Colour	Blue
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2022-04-23

Pictures 39

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-05-05
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	36
Total items failed	6

MOT #17	2023-05-04 09:05
MOT test number	132472787304
Result	<b>✓</b> Passed
Next expiry date	2024-05-05
<b>Advice</b> Undertrays	

MOT #16	2022-05-06 13:46
MOT test number	272240539974
Result	<b>✓</b> Passed

MOT #15		2021-11-29 13:46
MOT test	number	479755826672
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Inner wall (5.2.3 (d) (ii)	)

MOT #14	2020-11-30 09:53
MOT test number	152546942040
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #13

MOT test number

Result

Advice

Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2018-11-28 10:22 **MOT** test number 722803466549 Result Passed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #11
 2017-11-28 11:29

 MOT test number
 242868796226

 Result
 ✓ Passed

MOT #10

MOT test number

934703069504

Result

Advice Nearside Front tyre cracking in tread

CarCheck.co.uk page 4/14



**MOT #7** 

**Notice** 

Notice

**GL57NBZ** 

report date: 2024-03-28

2015-01-12 10:20

MOT #9

MOT test number

640168694871

Result

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

**Advice** Nearside Front tyre cracking in tread

Rear pads worn low -1.8mm, renew asap

MOT #8 2015-11-27 14:09
MOT test number 343823678239
Result ✓ Passed

MOT test number 648862515014

Result ✓ Passed

MOT #6 2013-12-24 10:17


**MOT** test number 729668553348 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Notice** Tow ball/hitch not fitted at time of test Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) **Advice** Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice Engine covers fitted obscuring some components in the engine bay Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/14

Under-trays fitted obscuring some underside components



report date: 2024-03-28




MOT #4	2013-01-07 15:29
MOT test number	485237003084
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #3	2013-01-07 14:58	
MOT test number	788017903052	
Result	🗙 Failed	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Fail Offside Front Headlamp not working on dipped beam (1.7.5a)		
Notice Child seat fitted not allowing full inspection of adult belt		

CarCheck.co.uk page 6/14



report date: 2024-03-28



MOT #1		2011-01-14 16:22
MOT test number		528534511051
Result		<b>✓</b> Passed
Notice Both from	nt tyres are wearing on the inner and outer edge	es
<b>Notice</b> Front bra	ake pads are low	

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	5 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	IIK SIA:
Plate since	
Current registration	UK NIS
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-13
Last registration	2023-05-04
Complete history	See info



Registration #1	2007-12-13	7 mi
Registration #2	2011-01-14	28.474 mi
Registration #3	2011-12-16	37.312 mi
Registration #4	2013-01-07	44.969 mi
Registration #5	2013-01-07	44.969 mi
Registration #6	2013-12-23	5.115 mi
Registration #7	2013-12-24	5.115 mi
Registration #8	2015-01-12	10.426 mi
Registration #9	2015-11-27	12.126 mi
Registration #10	2016-11-30	24.815 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		91.777 es
Registration #18		10.777 mg

More info >

CarCheck.co.uk page 13/14



## Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1760 mm
Height	1495 mm
Length	4750 mm
Wheel base	2720 mm
Kerb weight	1602 kg

## Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	N22A13104613

CarCheck.co.uk page 14/14