





report date: 2024-03-29

General information

Make	BMW
Model	530 530D M SPORT
Colour	Black
Year of manufacture	2007
Top speed	154 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	235 BHP
Max. torque	500 Nm at 3.000 rpm
Engine capacity	2.497 cc
Cylinders	6
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-27

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2022-07-24
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #15	2021-06-26 10:49
MOT test number	459094273018
Result	✓ Passed
Next expiry date	2022-07-24
Advice Offside Front Upper Suspension arm pin or bush worn but not result front bush (5.3.4 (a) (i))	ulting in excessive movement

MOT #14	2020-06-26 13:01
MOT test number	590097666640
Result	✓ Passed
Advice Offside Rear Lower Suspension arm pin or bush worn but not results. (5.3.4 (a) (i))	
Advice Nearside Rear Lower Suspension arm pin or bush worn but not re (5.3.4 (a) (i))	sulting in excessive movement

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2020-06-22 12:11

MOT test number 890672516637

Result X Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #12 2019-07-25 08:13

MOT test number 819467094653

Result \(\sqrt{Passed} \)

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #11 2018-03-24 13:10

MOT test number 832445708294

Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

Advice Under body tray fitted, not allowing full inspection.

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10

MOT test number

973890652812

Result

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

Fail Rear Parking brake (secondary) brakes imbalanced (3.7.B.6b)

Advice Under body tray fitted, not allowing full inspection.

MOT #9

MOT test number

Result

Advice Emissons test carred out zero reading

2017-04-22 15:05

162564999858

✓ Passed

MOT #8

MOT test number

Fesult

Advice Strong advise wear to n/s/r o/s/r tyres on inner edges

Advice Perishing to n/s/f tyre

MOT #7

MOT test number

416141025134

Result

Notice Signs of wear and feathering to o/s/f tyre on outer edge

CarCheck.co.uk page 5/13



MOT #6

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #F	2012 OF 16 17.00
MOT #5 MOT test number	2013-05-16 17:09 389276433144
Result	✓ Passed
	2012 05 10 10 00
MOT #4	2012-05-18 10:20
MOT test number	648969732183
Result	✓ Passed
MOT #3	2011-05-10 16:32
MOT test number	169220431170
Result	✓ Passed
MOT #2	2011-05-09 12:28
MOT test number	288589821450
Result	× Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #1	2010-05-20 10:00
MOT test number	142190740190
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



X MOT

Tax expired: 2 July 2021

Tax status

Expired:
24 July 2022

Expired at 2 July 2021

Days left 1032 days too late

MOT expiry date 24 July 2022

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1

Date

Category
Type

Damage 2

Date

Category

Туре



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners defined the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In kilometers
Mileage registrations	17
First mileage registration	2007-03-21
Last registration	2021-06-26
Complete history	See info



Registration #1	2007-03-21	26 mi
Registration #2	2010-05-20	19.508 mi
Registration #3	2011-05-09	23.359 mi
Registration #4	2011-05-10	23.360 mi
Registration #5	2012-05-18	27.864 mi
Registration #6	2013-05-16	33.301 mi
Registration #7	2014-05-02	46.956 mi
Registration #8	2015-05-01	62.627 mi
Registration #9	2016-05-11	78.814 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #11 Registration #12		10,777 es
		11.777 es
Registration #12		10,777 es
Registration #12 Registration #13		10,777 es
Registration #12 Registration #13 Registration #14		10,777-66 10,777-66 10,777-66 10,777-66 10,777-66

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1469 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1675 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 13/1