



report date: 2024-03-29

General information

Make	NISSAN
Model	PULSAR ACENTA DIG-T
Colour	Blue
Year of manufacture	2018
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.198 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-01-17
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	3

MOT #4	2023-08-29 14:39
MOT test number	139660526750
Result	✓ Passed
Next expiry date	2024-08-31
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3	2022-08-08 12:20
MOT test number	140128655695
Result	✓ Passed
Advice	Headlamp Bracket Broken But Light Unit Secure
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #2** 2022-08-06 12:20**MOT test number** 311073388365**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Headlamp Bracket Broken But Light Unit Secure**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**MOT #1** 2021-08-24 11:26**MOT test number** 441808122402**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 SV68SZX
Plate since	2019-03-29
Current registration	 SV68SZX
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-09-01
Last registration	2023-08-29
Complete history	See info



Registration #1	2018-09-01	24 mi
Registration #2	2021-08-24	10.414 mi
Registration #3	2023-08-29	25.277 mi
Registration #4	2023-08-29	25.277 mi
Registration #5	2023-08-29	25.277 mi
Registration #6	2023-08-29	25.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1768 mm
Height	1520 mm
Length	4387 mm
Wheel base	2700 mm
Kerb weight	1304 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	607979A