





report date: 2024-03-28

General information

Make	CUPRA
Model	FORMENTOR VZ2 TSI 4DRIVE S-A
Colour	Black
Year of manufacture	2021
Top speed	155 mph
Gearbox	7 speed SEMI AUTO

Engine & fuel consumption

Power	306 BHP
Max. torque	400 Nm at 5.450 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption combined	33.2 mpg
CO2 emission	193 g/km
CO2 label	1



CarCheck.co.uk page 1/11



Internet history

Entry 4

Date 2021-10-30

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

Date 2021-08-13

Pictures 20

Listing price <u>View report</u>









source: heycar.co.uk

Entry 2

Date 2021-07-24

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-17
Pictures	0

CarCheck.co.uk page 2/11

source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-28
MOT pass rate	50 %
MOT passed	1
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #2		2024-01-02 15:13
MOT test i	number	794355694105
Result		✓ Passed
Next expi	y date	2025-01-28
Advice (i))	Offside Rear Tyre has a cut but not deep enough to reach the ply or cor	ds cut to sidewall (5.2.3 (d)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Nail in tyre	
Advice (d) (i))	Nearside Rear Tyre has a cut but not deep enough to reach the ply or co	ords cut to sidewall (5.2.3
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Nail in tyre	

CarCheck.co.uk page 3/11



MOT #1 2024-01-02 15:13

MOT test number 470718823697

Result X Failed

Pass with rectification Offside Front Windscreen washer not working (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords cut to sidewall (5.2.3 (d)

(i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Nail in tyre

Pass with rectification Nearside Front Windscreen washer not working (3.5 (a))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords cut to sidewall (5.2.3

(d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Nail in tyre

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
First licence fee (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CUPRA. See if, where and when this CUPRA had damage and the car repair costs. We also check if this CUPRA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CUPRA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CUPRA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this CUPRA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this CUPRA had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this CUPRA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CUPRA has been settled.

If not, and you buy this CUPRA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CUPRA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2021-01-29
Last registration	2024-01-02
Complete history	See info



Registration #1	2021-01-29	8 mi
Registration #2		71.777 es
Registration #3		11.177 es
Registration #4		11.777 es
Registration #5		11.777 ms
Registration #6		11.777 es
Registration #7		11,177 ms

More info >

CarCheck.co.uk page 10/11



		_		
- I) Im	ension	с Х.	WAIG	nt.
	CHSIUH	3 W	weiu	III.

Width	1839 mm
Height	1511 mm
Length	4450 mm
Max. allowed weight	2140 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	DNFB009749

CarCheck.co.uk page 11/11