





General information

Make	PEUGEOT
Model	108 ALLURE
Colour	Red
Year of manufacture	2017
Top speed	105 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	82 BHP
Max. torque	116 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







Internet history

Entry 3		
Date	2021-02-03	
Pictures	10	
Listing price	View report	




source: autoonline.co.uk

Entry 2	
Date	2021-01-22
Pictures	1
Listing price	View report

bu	yccar with confidence.
-	Peace of mind At an early early to design with special characteristic and service they early an early and an early early with a studieg where guarantee
:ef	The very best prices Marker loans script or with an allocation example payment stars, and a market of a 1% for the term prov.
æ	Zero hassle With with any wany date of the area, then arranging the france of the relation and state of the area.
	6

source: yesauto.com

Entry 1			
Date	2021-01-22		
Pictures	16		
Listing price	View report		



source: yesauto.com



MOT history

MOT expiry date	2024-12-17
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	2

МОТ #5	2023-12-06 12:26
MOT test number	854318132229
Result	🗸 Passed
Next expiry date	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4		2022-12-03 10:32
MOT test	number	993217178528
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #3	2022-12-03 09:48
MOT test number	523139377895
Result	🗙 Failed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
FailNearside Rear Tyre has a cut in excess of the requirements deep enough to read(5.2.3 (d) (i))	ch the ply or cords
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2	2021-11-18 15:22
MOT test number	358523752613
Result	✓ Passed

MOT #1		2020-11-23 14:58
MOT test	number	189405034754
Result		✓ Passed
Advice	Exhaust mounting defective (6.1.2 (a))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓ Taxed	✓ МОТ
Tax due: 1 March 2025	Expires: 17 December 2024
Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	
Category	 AMPL
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and and a second s	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

12-18
12-06
<u>nfo</u>



Registration #1	2017-12-18	7 mi
Registration #2	2020-11-23	19.091 mi
Registration #3		11.777 mi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	78%
Pedestrian	61%
Safety systems	83%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1615 mm
Height	1460 mm
Length	3475 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1240 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	B2220018458