



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MODUS DYNAMIQUE 16V
Colour	Blue
Year of manufacture	2006
Top speed	110 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	127 Nm at 4.250 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-01-21
Pictures	4
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2023-05-20
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	24
Total items failed	19

MOT #22	2022-05-21 11:36
MOT test number	297100299591
Result	✓ Passed
Next expiry date	2023-05-20
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2022-05-10 13:36
MOT test number	844581083524
Result	✗ Failed
Fail	Tyre tread depth below requirements of 1.6mm both fronts (5.2.3 (e))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #20** 2021-05-12 10:34**MOT test number** 316123765183**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened deteriorated (1.1.14 (a) (ii))**Advice** Front Brake pipe corroded, covered in grease or other material covered in grease (1.1.11 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #19** 2019-11-11 09:05**MOT test number** 351667063067**Result** ✓ Passed**MOT #18** 2019-11-07 12:41**MOT test number** 645373705552**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**MOT #17** 2018-11-14 14:07**MOT test number** 528778226654**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2018-11-12 13:54**MOT test number** 801346130501**Result** ✗ Failed

- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Exhaust corroded
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #15** 2017-10-20 08:13**MOT test number** 182838314354**Result** ✓ Passed**MOT #14** 2017-10-19 10:33**MOT test number** 802034708316**Result** ✗ Failed

- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)

**MOT #13** 2016-10-19 08:56**MOT test number** 888774348036**Result** ✓ Passed

**MOT #12** 2015-10-19 12:44**MOT test number** 822950438674**Result** ✓ Passed**MOT #11** 2014-11-18 10:33**MOT test number** 519892024358**Result** ✓ Passed**MOT #10** 2014-03-21 14:37**MOT test number** 896790584040**Result** ✓ Passed

- Notice** Spare wheel rim damaged
- Notice** Nearside head light beam pattern slightly distorted
- Notice** Offside front tyre badly scrubbed on inside edge

**MOT #9** 2014-03-19 11:57**MOT test number** 629238774015**Result** ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Rear Seat belt locking mechanism does not secure or release (5.2.5a)
- Notice** Offside front tyre badly scrubbed on inside edge
- Fail** Upper Stop lamp not working (1.2.1b)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Spare wheel rim damaged
- Notice** Nearside head light beam pattern slightly distorted

**MOT #8** 2013-03-21 14:36**MOT test number** 599650583055**Result** ✓ Passed**MOT #7** 2013-03-12 09:40**MOT test number** 915901073009**Result** ✗ Failed**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2012-03-13 08:49**MOT test number** 195033972405**Result** ✓ Passed**MOT #5** 2011-10-27 14:01**MOT test number** 426470701313**Result** ✓ Passed**Advice** Nearside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Nearside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #4** 2010-11-22 09:42**MOT test number** 480086420352**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #3** 2010-11-22 09:42**MOT test number** 280116120340**Result** ✓ Passed



MOT #2	2010-02-26 12:13
MOT test number	773907750065
Result	✓ Passed
Notice	Off side front tyre on legal limit and bald on edge
Notice	Near side front tyre bald on edge

MOT #1	2009-02-27 15:29
MOT test number	704578459096
Result	✓ Passed
Notice	Both front discs lipped





Tax & MOT check

✕  
Untaxed

Tax expired:  
1 February 2023

✕  
MOT

Expired:  
20 May 2023

Tax status	Expired at 1 February 2023
Days left	454 days too late
MOT expiry date	20 May 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-03-01
Last registration	2022-05-21
Complete history	<a href="#">See info</a>



Registration #1	2006-03-01	20 mi
Registration #2	2009-02-27	17.094 mi
Registration #3	2010-02-26	22.153 mi
Registration #4	2010-11-22	25.964 mi
Registration #5	2011-10-27	38.211 mi
Registration #6	2012-03-13	39.627 mi
Registration #7	2013-03-12	49.338 mi
Registration #8	2013-03-21	49.703 mi
Registration #9	2014-03-19	55.592 mi
Registration #10	2014-03-21	55.592 mi
Registration #11	2014-11-18	56.558 mi
Registration #12	2015-10-19	58.779 mi
Registration #13	2016-05-20	59.377 mi
Registration #14	2016-05-20	59.377 mi
Registration #15	2016-05-20	59.377 mi
Registration #16	2016-05-20	59.377 mi
Registration #17	2016-05-20	59.377 mi
Registration #18	2016-05-20	59.377 mi
Registration #19	2016-05-20	59.377 mi
Registration #20	2016-05-20	59.377 mi
Registration #21	2016-05-20	59.377 mi
Registration #22	2016-05-20	59.377 mi
Registration #23	2016-05-20	59.377 mi
Registration #24	2016-05-20	59.377 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1960 mm
Height	1589 mm
Length	3792 mm
Wheel base	2482 mm
Kerb weight	1160 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D048527