



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 AUTHORITIES
Colour	Black
Year of manufacture	2012
Top speed	137 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-02-15
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	1

MOT #10	2023-02-09 12:05
MOT test number	231895672108
Result	✓ Passed
Next expiry date	2024-02-15

MOT #9	2023-02-09 12:05
MOT test number	820000581763
Result	✗ Failed
Pass with rectification	Offside Front Outline marker lamp not working (4.2.1 (a) (ii))

MOT #8	2022-02-14 11:49
MOT test number	714558901594
Result	✓ Passed

MOT #7	2022-02-12 12:18
MOT test number	981112664053
Result	✗ Failed
Advice	Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2021-02-16 12:56**MOT test number** 603861088077**Result** ✓ Passed**MOT #5** 2020-01-21 10:57**MOT test number** 832026757017**Result** ✓ Passed**MOT #4** 2019-01-22 10:23**MOT test number** 330978005247**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both wearing thin (1.1.14 (a) (ii))**MOT #3** 2018-02-08 09:52**MOT test number** 359011217874**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt both sides**MOT #2** 2017-02-28 15:34**MOT test number** 961103393256**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #1** 2015-12-03 16:59**MOT test number** 955109429378**Result** ✓ Passed**Advice** Undertrays fitted



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-01-01
Last registration	2023-02-09
Complete history	<a href="#">See info</a>



Registration #1	2012-01-01	27 mi
Registration #2	2015-12-03	54.580 mi
Registration #3	2017-02-28	40.507 mi
Registration #4	2018-02-08	75.682 mi
Registration #5	2019-01-22	88.242 mi
Registration #6	2020-01-21	100.621 mi
Registration #7	2020-01-21	100.621 mi
Registration #8	2020-01-21	100.621 mi
Registration #9	2020-01-21	100.621 mi
Registration #10	2020-01-21	100.621 mi
Registration #11	2020-01-21	100.621 mi
Registration #12	2020-01-21	100.621 mi

More info >





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm

Additional information

Number of seats	5
Number of axles	2
Engine number	1091388