



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 T SE SPORT
Colour	Black
Year of manufacture	-
Top speed	146 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 4.500 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-08-09
Pictures	9
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #15	2023-04-27 09:42
MOT test number	717480540879
Result	✓ Passed
Next expiry date	2024-04-26
Advice	Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

MOT #14	2021-09-22 08:33
MOT test number	804189572879
Result	✓ Passed
Advice	Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Lower UNDER TRAYS & OUTER COVER SILLS FITTED AT TIME OF TEST
Advice	Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #13	2020-09-24 08:44
MOT test number	498994400300
Result	✓ Passed
Advice	Lower UNDER TRAYS FITTED

MOT #12	2019-09-25 16:24
MOT test number	523821603899
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded SLIGHTLY (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded SLIGHTLY (5.3.1 (b) (i))

**MOT #11** 2018-09-26 15:10**MOT test number** 383845994232**Result** ✓ Passed**Advice** Under sheild fitted**Advice** Both front tyres worn out of shape**MOT #10** 2017-09-28 12:14**MOT test number** 393524864406**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2016-09-26 09:55**MOT test number** 768812592596**Result** ✓ Passed**MOT #8** 2015-09-28 09:41**MOT test number** 420838568714**Result** ✓ Passed**Advice** Engine cover and tray fitted obscuring some components**MOT #7** 2014-09-17 16:24**MOT test number** 466560964259**Result** ✓ Passed**MOT #6** 2014-09-17 16:24**MOT test number** 547770264262**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)



MOT #5	2013-09-25 15:05
MOT test number	396488563440
Result	✓ Passed
MOT #4	2012-09-07 11:05
MOT test number	267751952279
Result	✓ Passed
MOT #3	2011-09-21 09:11
MOT test number	247814661298
Result	✓ Passed
MOT #2	2010-09-29 10:42
MOT test number	611182670206
Result	✓ Passed
MOT #1	2009-09-25 11:21
MOT test number	443818869265
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-09-27
Last registration	2023-04-27
Complete history	See info



Registration #1	2006-09-27	25 mi
Registration #2	2009-09-25	15.030 mi
Registration #3	2010-09-29	23.713 mi
Registration #4	2011-09-21	33.352 mi
Registration #5	2012-09-07	40.475 mi
Registration #6	2013-09-25	57.149 mi
Registration #7	2014-09-17	71.598 mi
Registration #8	2015-09-28	85.794 mi
Registration #9	2016-09-28	99.999 mi
Registration #10	2017-09-28	114.199 mi
Registration #11	2018-09-28	128.399 mi
Registration #12	2019-09-28	142.599 mi
Registration #13	2020-09-28	156.799 mi
Registration #14	2021-09-28	170.999 mi
Registration #15	2022-09-28	185.199 mi
Registration #16	2023-04-27	199.399 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1540 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	4065831
---------------	---------