



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO VISIA
Colour	Silver
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-11-25
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-02
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	30
Total items failed	5

MOT #14 2023-08-18 14:38

MOT test number 247140733997

Result ✓ Passed

Next expiry date 2024-09-02

- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material axle (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13 2022-08-31 14:52

MOT test number 684256121663

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 155/65/14 (5.2.3 (e))



MOT #12	2022-08-26 15:51
MOT test number	667963286407
Result	✗ Failed
MAJOR	Offside Rear Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength MOUNTING POINT ON AXLE (5.3.6 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 155/65/14 (5.2.3 (e))
MAJOR	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength MOUNTING POINT ON AXLE (5.3.6 (a) (i))

MOT #11	2021-09-03 12:34
MOT test number	362389082542
Result	✓ Passed
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))
Advice	Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Coil spring corroded (5.3.1 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10**

2021-09-02 15:33

MOT test number

710298685792

Result**✗ Failed****Pass with rectification**

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Front Coil spring corroded (5.3.1 (b) (i))

MAJOR

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Nearside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))

Advice

Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MAJOR

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #9

2020-08-24 11:06

MOT test number

887183993192

Result**✓ Passed****MOT #8**

2019-07-01 08:30

MOT test number

520696441632

Result**✓ Passed****Advice**

All 4 coil springs slightly corroded

MOT #7

2018-06-25 08:50

MOT test number

603199584403

Result**✓ Passed****Advice**

Both front inner cv boots slight grease, bands slightly losing tension

Advice

Marks on bodywork: nsf bumper scuff

**MOT #6** 2017-07-04 08:58**MOT test number** 306317596152**Result** ✓ Passed**MOT #5** 2016-07-11 11:30**MOT test number** 243050337212**Result** ✓ Passed**Advice** Clutch biting point high**Advice** Marks on bodywork: nsf bumper scuff**MOT #4** 2015-07-14 10:17**MOT test number** 855395395125**Result** ✓ Passed**MOT #3** 2015-07-13 09:33**MOT test number** 699254095184**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #2** 2014-07-11 15:37**MOT test number** 845492794165**Result** ✓ Passed



MOT #1	2014-07-11 10:46
MOT test number	307472594173
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
2 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	2 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	YF11WSE
Plate since	2019-03-29
Current registration	YF11WSE
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-08-12
Last registration	2023-08-18
Complete history	See info



Registration #1	2011-08-12	28 mi
Registration #2	2014-07-11	8.329 mi
Registration #3	2014-07-11	8.329 mi
Registration #4	2015-07-13	11.027 mi
Registration #5	2015-07-14	11.027 mi
Registration #6	2016-07-11	13.615 mi
Registration #7	2017-07-04	16.241 mi
Registration #8	2018-06-25	18.234 mi
Registration #9	2019-06-25	20.227 mi
Registration #10	2019-06-25	20.227 mi
Registration #11	2019-06-25	20.227 mi
Registration #12	2019-06-25	20.227 mi
Registration #13	2019-06-25	20.227 mi
Registration #14	2019-06-25	20.227 mi
Registration #15	2019-06-25	20.227 mi
Registration #16	2019-06-25	20.227 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	133813