





General information

| Make | MAZDA |
|---------------------|----------------|
| Model | 2 D SPORT |
| Colour | Blue |
| Year of manufacture | 2015 |
| Top speed | 111 mph |
| 0 - 60 mph | 10.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 104 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 1.400 rpm |
| Engine capacity | 1.497 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 74.3 mpg |
| Consumption extra urban | 88.3 mpg |
| Consumption combined | 83.1 mpg |
| CO2 emission | 89 g/km |
| CO2 label | А |







Internet history

Entry 1

Date Pictures 2021-06-14

30


Listing price

View report









source: yesauto.com



MOT history

| MOT expiry date | 2024-05-18 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 0 |

| MOT #8 | 2023-05-18 07:51 |
|------------------|------------------|
| MOT test number | 840002131250 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-18 |

| MOT #7 | 2022-05-13 11:40 |
|-----------------|------------------|
| MOT test number | 547440108498 |
| Result | ✓ Passed |

| МОТ #6 | 2021-05-19 11:23 |
|-----------------|------------------|
| MOT test number | 741626683766 |
| Result | ✓ Passed |

| MOT #5 | 2020-11-11 13:21 |
|--|------------------|
| MOT test number | 114152497680 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



| GU | 15] | DX |
|--------|----------------|-----------|
| report | date: 2 | 024-03-29 |

| MOT #4 | | 2020-11-10 11:45 |
|----------|---|------------------|
| MOT test | number | 857516833431 |
| Result | | 🗙 Failed |
| Advice | Brake pad(s) wearing thin both front (1.1.13 (a) (ii)) | |
| MAJOR | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice | Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.1 | 4 (a) (ii)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #3 | 2019-11-12 13:06 | |
|--|------------------|--|
| MOT test number | 566347003802 | |
| Result | ✓ Passed | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| | | |

| MOT #2 | 2018-11-22 15:51 |
|-----------------|------------------|
| MOT test number | 584728435691 |
| Result | ✓ Passed |
| | |

| MOT #1 | 2018-03-12 10:11 |
|-----------------|------------------|
| MOT test number | 226834377859 |
| Result | ✓ Passed |



Tax & MOT check

| | ✓ Taxed | | ✓ МОТ |
|--------------------------------|------------|--------------------------------|--------------------|
| Tax due: 1 June 2024 | | Expires: 18 May 2024 | |
| Tax status | | | Valid until 1 June |
| Days left | | | 33 |
| MOT expiry date | | | 18 May 2024 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |
| Vehicle class | | 49 | |

| Venicle class | 45 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FEIDO |
| Category | 4 ARAPE |
| Туре | |
| Damage 2 | AMPL |
| | F Store |
| Date | 1. E |
| Category | ame |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-04-24 |
| Last registration | 2023-05-18 |
| Complete history | See info |



| Registration #1 | 2015-04-24 | 6 mi |
|------------------|------------|------------|
| Registration #2 | 2018-03-12 | 27.329 mi |
| Registration #3 | 2018-11-22 | 34.968 mi |
| Registration #4 | 2019-11-12 | 49.393 mi |
| Registration #5 | 2020-11-10 | 66.224 mi |
| Registration #6 | | 11.177 esi |
| Registration #7 | | 11.177 mi |
| Registration #8 | | 11.177 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 est |

More info >





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|--|--------------------------|
| Width | 1695 mm |
| Height | 1495 mm |
| Length | 4060 mm |
| Wheel base | 2570 mm |
| Kerb weight | 1115 kg |
| Max. allowed weight | 1575 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 44 |
| | 44 I Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |