





report date: 2024-03-28

General information

Make	MINI
Model	JOHN COOPER WORKS
Colour	Black
Year of manufacture	2017
Top speed	153 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	320 Nm at 1.250 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1


Date 2022-05-21

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



KP67WND report date: 2024-03-28

MOT history

MOT expiry date	2025-03-14
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #6	2024-03-15 08:58
MOT test number	714751138368
Result	✓ Passed
Next expiry date	2025-03-14
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	

MOT #5	2023-03-15 16:10
MOT test number	243250940447
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2023-03-15 12:12	
MOT test number	972685745230	
Result	X Failed	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its s	structure (5.2.3 (d) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Fail Offside Front Tyre has a lump, caused by separation or partial failure of its str	ructure (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number
648916525583

Result

MOT #2

MOT test number
2021-12-07 13:19

MOT test number
352541524199

Result

Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1	2020-12-08 09:33
MOT test number	981460008048
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

*	
For how long did the current and previous owner(s) have this MINI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	UK NE
Plate since	
	More info

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-16
Last registration	2024-03-15
Complete history	See info



Registration #1	2017-11-16	21 mi
Registration #2	2020-12-08	13.605 mi
Registration #3	2021-12-07	14.866 mi
Registration #4	2021-12-07	14.866 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3874 mm
Wheel base	1932 mm
Kerb weight	1295 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	44	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4	page 11/11

Number of axles 2

Engine number F508H516