



General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-04
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-23
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	39
Total items failed	6

MOT #18	2024-03-19 15:33
MOT test number	337954540149
Result	✓ Passed
Next expiry date	2025-03-23

MOT #17	2023-03-24 17:54
MOT test number	532148364408
Result	✓ Passed

**MOT #16**

2022-06-16 14:20

MOT test number

331339924450

Result

✓ Passed

- Advice** Coil spring corroded Both rear (5.3.1 (b) (i))
- Advice** Corrosion to rear beam axle
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Parking brake lever has little reserve travel
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive Nearside and offside inner sills (5.3.6 (a) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside front inner wheel arch liner damaged
- Advice** Items removed from driver's view prior to test
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside rear reflector damaged

MOT #15

2021-12-15 09:50

MOT test number

435701422484

Result

✓ Passed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-01-05 11:58**MOT test number** 565568047060**Result** ✓ Passed**MOT #13** 2021-01-04 13:37**MOT test number** 825378073911**Result** ✗ Failed**Fail** Nearside Rear Outer Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MOT #12** 2019-06-17 12:49**MOT test number** 954310748478**Result** ✓ Passed**Advice** Offside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Lower Under tray hanging loose**Advice** Nearside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Exhaust box corroded and peeling**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11** 2019-06-17 08:40**MOT test number** 812548405896**Result** ✗ Failed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Lower Under tray hanging loose
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corrosion (5.3.2 (b))
- Advice** Rear Exhaust box corroded and peeling
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10 2018-06-17 10:21**MOT test number** 765130970967**Result** ✓ Passed**MOT #9** 2017-06-27 10:17**MOT test number** 629982384601**Result** ✓ Passed

- Advice** Coolant leak

**MOT #8** 2017-06-27 10:17**MOT test number** 515296347305**Result** ✗ Failed**Advice** Coolant leak**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #7** 2016-05-31 12:20**MOT test number** 245548241340**Result** ✓ Passed**MOT #6** 2016-05-26 07:55**MOT test number** 318430686775**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #5** 2015-06-11 15:20**MOT test number** 959892365132**Result** ✓ Passed**MOT #4** 2014-06-10 15:59**MOT test number** 977091064140**Result** ✓ Passed**Notice** Rear exhaust corroded**MOT #3** 2014-06-10 13:44**MOT test number** 799491964116**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Rear exhaust corroded



MOT #2	2014-06-06 15:04
MOT test number	875917654158
Result	✗ Failed
<div><div>Notice</div>Oil leak</div> <div><div>Fail</div>Offside Front coil spring broken (2.4.C.1a)</div>	

MOT #1	2013-06-12 11:23
MOT test number	766933863157
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
17 April 2024

✓

MOT

Expires:
23 March 2025

Tax status	Expired at 17 April 2024
Days left	13 days too late
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-25
Last registration	2024-03-19
Complete history	See info



Registration #1	2010-06-25	10 mi
Registration #2	2013-06-12	28.487 mi
Registration #3	2014-06-06	38.551 mi
Registration #4	2014-06-10	38.669 mi
Registration #5	2014-06-10	38.669 mi
Registration #6	2015-06-11	45.751 mi
Registration #7	2016-05-26	53.652 mi
Registration #8	2016-05-31	53.663 mi
Registration #9	2017-06-27	55.660 mi
Registration #10	2017-06-27	55.660 mi
Registration #11	2018-06-27	55.660 mi
Registration #12	2018-06-27	55.660 mi
Registration #13	2018-06-27	55.660 mi
Registration #14	2018-06-27	55.660 mi
Registration #15	2018-06-27	55.660 mi
Registration #16	2018-06-27	55.660 mi
Registration #17	2018-06-27	55.660 mi
Registration #18	2018-06-27	55.660 mi
Registration #19	2018-06-27	55.660 mi
Registration #20	2018-06-27	55.660 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5839116