



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-01-26
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-12-03
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	32
Total items failed	19

MOT #17 2023-12-04 17:03**MOT test number** 246580960750**Result** ✓ Passed**Next expiry date** 2024-12-03**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front radiator cap modified**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16** 2023-12-01 10:44**MOT test number** 744442279322**Result** ✗ Failed**Fail** Front Headlamp aim unable to be tested (4.1.2 (b))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front radiator cap modified

**MOT #15**

2022-11-24 09:33

MOT test number

618721612796

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14**

2021-12-02 08:33

MOT test number

624540224007

Result

✓ Passed

Advice Front and rear tyres odd sizes**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**MOT #13**

2021-12-01 17:31

MOT test number

688715774847

Result

✗ Failed

Fail Nearside Side repeater incorrect colour (4.4.3 (a))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front and rear tyres odd sizes**Fail** Offside Side repeater incorrect colour (4.4.3 (a))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #12** 2021-01-15 12:21**MOT test number** 410950388446**Result** ✓ Passed**Advice** Nearside front tyre worn low on outer edge**Advice** Offside front tyre worn low on inner edge**MOT #11** 2021-01-07 16:16**MOT test number** 735983644241**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Central Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt insecure (5.3.4 (b) (ii))**Advice** Offside front tyre worn low on inner edge**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Rear Nail in tyre**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Nearside Front Road wheel fixing missing stud (5.2.1 (a) (i))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside front tyre worn low on outer edge**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #10** 2017-08-12 13:33**MOT test number** 907905411091**Result** ✓ Passed

**MOT #9** 2017-02-15 11:06**MOT test number** 510338051336**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #8 2017-02-15 09:51**MOT test number** 649756208672**Result** ✗ Failed

- Fail** Offside Rear Brake performance not tested parking brake staying on (3.7.A.1)
- Fail** Offside Rear Mechanical brake component has restricted free movement parking brake staying on (3.5.1k)

MOT #7 2016-06-27 15:25**MOT test number** 859444840349**Result** ✓ Passed**MOT #6** 2016-06-27 15:25**MOT test number** 668091511465**Result** ✗ Failed

- Pass with rectification** Nearside Front Direction indicator not working (1.4.A.2c)

**MOT #5** 2015-12-28 11:49**MOT test number** 461375227380**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)**MOT #4** 2015-12-28 11:49**MOT test number** 474634839433**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Offside Rear rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)**MOT #3** 2015-12-12 13:46**MOT test number** 344364533357**Result** ✓ Passed**MOT #2** 2014-12-31 14:11**MOT test number** 979035964329**Result** ✓ Passed**MOT #1** 2014-07-05 13:06**MOT test number** 205886284120**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
3 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	3 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	LR12JKX
Plate since	2019-03-28
Current registration	LR12JKX
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-30
Last registration	2023-12-04
Complete history	See info



Registration #1	2012-03-30	6 mi
Registration #2	2014-07-05	13.534 mi
Registration #3	2014-12-31	28.549 mi
Registration #4	2015-12-12	35.519 mi
Registration #5	2015-12-28	35.532 mi
Registration #6	2015-12-28	35.532 mi
Registration #7	2016-06-27	47.358 mi
Registration #8	2016-06-27	47.358 mi
Registration #9	2017-02-15	59.519 mi
Registration #10	2017-02-15	59.528 mi
Registration #11	2019-05-29	59.557 mi
Registration #12	2019-05-29	59.557 mi
Registration #13	2019-05-29	59.557 mi
Registration #14	2019-05-29	59.557 mi
Registration #15	2019-05-29	59.557 mi
Registration #16	2019-05-29	59.557 mi
Registration #17	2019-05-29	59.557 mi
Registration #18	2019-05-29	59.557 mi
Registration #19	2019-05-29	59.557 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number	D4CBC965952
---------------	-------------