





report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Silver
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date	2021-09-11
Pictures	6

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-09
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-14
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #13	2022 06 14 12:26
MOT #13 MOT test number	2023-06-14 13:36
Result	✓ Passed
Next expiry date	2024-06-14
Advice Nearside Rear Nail in tyre and o/s/r	
Advice Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair 29% imbalance (1.2.1 (c))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened and o/s/r (and corroded) (1.1.14 (a) (ii))	
Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	

MOT #12		2023-06-14 08:22
MOT test	number	790505223980
Result		× Failed
Advice	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice adjustmen	Front Service brake requirements only just met. It would appear that the brant or repair 29% imbalance $(1.2.1 (c))$	king system requires
Fail R	ear Service brake excessively fluctuating (1.2.1 (e))	
Advice	Nearside Rear Nail in tyre and o/s/r	
Advice corroded)	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened $(1.1.14 \ (a) \ (ii))$	and o/s/r (and

CarCheck.co.uk page 3/13



LS61ZTC

report date: 2024-03-29

MOT #11 2022-06-14 09:24

MOT test number 523176465236

Result \rightarrow Passed

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened and o/s/r (1.1.14 (a)

(ii))

MOT #10 2021-06-11 14:32

MOT test number 384930282791

Result

Passed

Advice Plastic trims shields and guards covering some prescribed areas.

MOT #9 2020-06-15 12:38

MOT test number 643370150678

Advice Plastic trims shields and guards covering some prescribed areas.

MOT #8 2020-06-15 11:35

MOT test number 651283349827

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Plastic trims shields and guards covering some prescribed areas.

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-05-13 15:06

MOT test number 415404945277

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened also pads not working full

width of discs (1.1.14 (a) (ii))

Advice Plastic trims shields and guards covering many prescribed areas.

CarCheck.co.uk page 4/13



LS61ZTC

report date: 2024-03-29

MOT #6 2019-05-13 09:52 968408179815 **MOT** test number Result × Failed **Advice** Service light on Advice Rear Brake disc worn, pitted or scored, but not seriously weakened also pads not working full width of discs (1.1.14 (a) (ii)) Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Plastic trims shields and guards covering many prescribed areas. **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #5

MOT test number

Result

Advice Front brake discs worn and corroded on edges

Advice Plastic trims shields and guards covering many perscribed areas

MOT #4		2017-05-11 10:52
MOT test	number	235152567572
Result		✓ Passed
Advice	Plastic trims shields and guards covering some prescribed areas.	
Advice	Nearside Front Tyre worn close to the legal limit and offside (4.1.E.1)	

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Plastic trims shields and guards covering some prescribed areas

Advice Poor beam pattern in headlamps

Advice Front Brake pad(s) wearing thin (3.5.1g)

 MOT #2
 2015-05-15 13:04

 MOT test number
 207235035139

 Result
 ✓ Passed

MOT #1

MOT test number

Result

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner matery	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK SIF
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



LS61ZTC

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-25
Last registration	2023-06-14
Complete history	See info



Registration #1	2011-10-25	14 mi
Registration #2	2014-09-29	25.325 mi
Registration #3	2015-05-15	28.405 mi
Registration #4	2016-05-09	34.806 mi
Registration #5	2017-05-11	40.099 mi
Registration #6	2018-05-10	45.127 mi
Registration #7	2019-05-13	49.941 mi
Registration #8	2019-05-13	49.944 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.77 66
Registration #12		11.777 es
Registration #13		9.77 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

page 12/13 CarCheck.co.uk



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/3

Number of axles 2

Engine number D246598