



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Black
Year of manufacture	2006
Top speed	139 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.4 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-05-18
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-24
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	29
Total items failed	3

MOT #18	2023-05-25 10:59
MOT test number	910610999871
Result	✓ Passed
Next expiry date	2024-05-24

MOT #17	2022-05-19 07:05
MOT test number	239263851472
Result	✓ Passed

**MOT #16**

2021-09-14 11:23

MOT test number

853128743249

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Exhaust has a minor leak of exhaust gases box (6.1.2 (a))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2020-09-08 11:35

MOT test number

941966291847

Result

✓ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear exhaust mount corroded off
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

2019-09-06 09:34

MOT test number

348398743665

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Exhaust mounting defective corroded off (6.1.2 (a))

**MOT #13** 2019-09-06 09:34**MOT test number** 872100913546**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Exhaust mounting defective corroded off (6.1.2 (a))**MOT #12** 2018-08-20 10:54**MOT test number** 158756879275**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #11** 2018-08-20 10:54**MOT test number** 319130664094**Result** ✗ Failed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10** 2017-09-04 15:16**MOT test number** 327671896108**Result** ✓ Passed

**MOT #9** 2017-09-04 09:34**MOT test number** 626707588124**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2016-09-02 13:45**MOT test number** 484804468237**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-09-08 10:56**MOT test number** 147631849067**Result** ✓ Passed**MOT #6** 2014-09-09 15:21**MOT test number** 349122854484**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside front tyre sidewall damaged**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-12-04 10:25**MOT test number** 258468433344**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre



MOT #4	2013-01-03 15:39
MOT test number	499013503053
Result	✓ Passed
MOT #3	2011-12-15 16:33
MOT test number	256489741354
Result	✓ Passed
MOT #2	2010-11-04 13:30
MOT test number	310678800360
Result	✓ Passed
MOT #1	2009-10-23 12:48
MOT test number	753726699226
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
24 May 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-10-31
Last registration	2023-05-25
Complete history	See info



Registration #1	2006-10-31	10 mi
Registration #2	2009-10-23	11.239 mi
Registration #3	2010-11-04	13.662 mi
Registration #4	2011-12-15	16.792 mi
Registration #5	2013-01-03	18.124 mi
Registration #6	2013-12-04	22.981 mi
Registration #7	2014-09-09	27.181 mi
Registration #8	2015-09-08	31.145 mi
Registration #9	2016-09-02	34.047 mi
Registration #10	2017-09-04	38.729 mi
Registration #11	2018-05-25	42.557 mi
Registration #12	2019-05-25	46.557 mi
Registration #13	2020-05-25	50.557 mi
Registration #14	2021-05-25	54.557 mi
Registration #15	2022-05-25	58.557 mi
Registration #16	2023-05-25	62.557 mi
Registration #17	2024-05-25	66.557 mi
Registration #18	2025-05-25	70.557 mi
Registration #19	2026-05-25	74.557 mi
Registration #20	2027-05-25	78.557 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1665 kg
Max. allowed weight	2135 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030735534