





General information

Make	ΤΟΥΟΤΑ
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Blue
Year of manufacture	2006
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP	0 < 101 A
Max. torque	150 Nm at 4.800 rpm	101 - 120 ^B _C
Engine capacity	1.598 cc	121 - 140 F
Cylinders	4	141 - 165 F
Fuel type	Petrol	166 - 185 ^H
Consumption city	31.4 mpg	186 - 225
Consumption extra urban	47.9 mpg	225+
Consumption combined	40.4 mpg	
CO2 emission	168 g/km	
CO2 label	Н	





Internet history

Entry 1	
Date	2021-06-09
Pictures	3
Listing price	View report







source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-26
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	26
Total items failed	12

МОТ #20	2024-02-12 15:46
MOT test number	127606686839
Result	✓ Passed
Next expiry date	2025-02-26
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or l (i))	light sources (4.7.1 (b)
Advice Rear Exhaust has a minor leak of exhaust gases Silencer joint (6.1.2 (a))	

MOT #19	2024-02-12 13:59
MOT test number	637166415041
Result	🗙 Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Parking (secondary brake) on a single line braking system has inadequat	e effort at a wheel
(1.3.1 (a) (i))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or lig	ht sources (4.7.1 (b)
(i))	
Fail Headlamp lens seriously defective Both headlights misted (4.1.1 (b) (ii))	
Advice Rear Exhaust has a minor leak of exhaust gases Silencer joint (6.1.2 (a))	

MOT #18	2023-02-20 13:25
MOT test number	843972512616
Result	✓ Passed
Minor Windscreen wiper blade defective Smeary (3.4 (b) (i))	





MOT #17	2022-02-15 13:14
MOT test number	219156267463
Result	✓ Passed
Minor Nearside Registration plate lamp inoperative in the case of multiple la (b) (i))	mps or light sources (4.7.1

MOT #16	2022-02-15 13:14
MOT test number	580642097540
Result	× Failed
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Minor Nearside Registra	ation plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

MOT #15	2021-02-19 15:21
MOT test	number 473976934905
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4

MOT #14	2020-02-25 15:18
MOT test number	693944204786
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

2019-02-18 10:10
893578297125
✓ Passed





MOT #12	2018-02-27 13:11
MOT test number	957418687302
Result	✓ Passed
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
MOT #11	2018-02-24 16:38
MOT test number	635445628014
Result	🗙 Failed
Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Offside Rear Stop lamp not working (1.2.1b)	
Advice Offside Rear Tyre worn close to the legal limit 2MM and sides worn (4.1.E.1)	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Parking brake lever has little reserve travel (3.1.6b)	
Fail Offside Front Front position lamp(s) not working (1.1.A.3b)	
FailBattery insecure (1.9.1)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	

MOT #10	2017-02-23 10:05
MOT test number	877362666306
Result	✓ Passed

MOT #9		2017-02-23 10:05
MOT test number		224835906117
Result		🗙 Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	



RO56HTE
report date: 2024-03-29

MOT #8	2016-02-24 12:12
MOT test number	406215664156
Result	✓ Passed
AdviceRear Brake pad(s) wearing thin (3.5.1g)AdviceOffside rear tyre cracking on sidewall	

MOT #7		2015-02-24 11:55
MOT test	number	329445655032
Result		✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2014-02-27 09:58
MOT test number	338428154051
Result	✓ Passed
Advice Parking brake lever has little reserve travel (3.1.6b)	

MOT #5	2014-02-27 09:33
MOT test number	127528054066
Result	🗙 Failed
AdviceParking brake lever has little reserve travel (3.1.6b)FailNearside Rear Tyre has ply or cords exposed (4.1.D.1b)	

MOT #4	2012-09-14 13:39
MOT test number	387938952471
Result	✓ Passed





MOT #3		2011-08-10 13:38
MOT test number		179842221260
Result		✓ Passed
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		
MOT #2		2010-08-27 14:18
MOT test number 823369330283		823369330281
Result		✓ Passed
MOT #1		2009-09-07 15:43
MOT test number		392330359254
Result		✓ Passed
Advice Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)		



Tax & MOT check

Tax due:	∕ xed	Expires:	✓ MOT
1 June 2024 Tax status		26 February 2025	Valid until 1 June
Days left			32
MOT expiry date			26 February 2025
Full MOT history			<u>See MOT history</u>

Tax calculation

Vehicle class	48
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-08
Last registration	2024-02-12
Complete history	See info



Registration #1	2006-09-08	17 mi
Registration #2	2009-09-07	14.644 mi
Registration #3	2010-08-27	18.550 mi
Registration #4	2011-08-10	20.442 mi
Registration #5	2012-09-14	57.731 mi
Registration #6	2014-02-27	38.428 mi
Registration #7	2014-02-27	38.428 mi
Registration #8	2015-02-24	46.209 mi
Registration #9	2016-02-24	52.206 mi
Registration #10	2017-02-23	58.912 mi
Registration #11	2017-02-23	58.912 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 mi
Registration #22		11.777 est





Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	3ZZU816369