






report date: 2024-03-28

General information

| Make | RENAULT |
|---------------------|-------------------------|
| Model | MASTER LH35 DCI H/R P/V |
| Colour | White |
| Year of manufacture | 2010 |
| Top speed | 82 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 125 BHP |
|-------------------------|---------------------|
| Max. torque | 310 Nm at 2.500 rpm |
| Engine capacity | 2.298 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 29.4 mpg |
| Consumption extra urban | 38.6 mpg |
| Consumption combined | 34.8 mpg |



CarCheck.co.uk page 1/20



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-23

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/20



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-04-19 |
|--------------------|------------|
| MOT pass rate | 52 % |
| MOT passed | 12 |
| Failed MOT tests | 11 |
| Total advice items | 55 |
| Total items failed | 66 |

| MOT #23 | | 2024-03-21 16:13 |
|-----------|--|------------------|
| MOT test | number | 582877400214 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-04-19 |
| Advice | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (| c)) |
| Advice | Offside Front Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Offside Front Shock absorbers has light misting of oil casing damaged (5.3.2 (b) |) |

CarCheck.co.uk page 3/20



report date: 2024-03-28

MOT #22 2024-03-20 15:11 **MOT** test number 972334858663 Result × Failed Fail Nearside Rear Outline marker lamp not working (4.2.1 (a) (ii)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Nearside Front Headlamp aim too high (4.1.2 (a)) Nearside Front Shock absorbers has a serious fluid leak casing damaged (5.3.2 (b)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Fail Offside Outline marker lamp not working central (4.2.1 (a) (ii)) Offside Front Coil spring corroded (5.3.1 (b) (i)) **Advice Advice** Offside Front Shock absorbers has light misting of oil casing damaged (5.3.2 (b)) Fail Offside Front Headlamp aim too low (4.1.2 (a)) Fail Offside Front Outline marker lamp not working (4.2.1 (a) (ii))

| MOT #21 | 2023-04-20 14:24 |
|-----------------|------------------|
| MOT test number | 738374758079 |
| Result | ✓ Passed |

MOT #20

MOT test number

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

| MOT #19 | 2022-09-08 12:03 |
|-----------------|------------------|
| MOT test number | 347648855905 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/20



Result

MK60LFN

report date: 2024-03-28

× Failed

MOT #18 2022-08-30 16:12

MOT test number 139274701972

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #17 2021-10-20 08:27

MOT test number 840013087180

Minor Offside Front Outline marker lamp incorrect colour (4.2.3 (a) (i))

MOT #16 2021-10-18 08:17

MOT test number 745084799003

Result X Failed


Fail Nearside Front Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))

Minor Offside Front Outline marker lamp incorrect colour (4.2.3 (a) (i))

CarCheck.co.uk page 5/20



report date: 2024-03-28



| MOT #14 | | 2020-09-12 12:53 |
|----------|--|------------------|
| MOT test | number | 129130435431 |
| Result | | ✓ Passed |
| Advice | Offside Front Outer cv boot perished | |
| Advice | Nearside Rear tyre worn on outer edge | |
| Advice | Offside Rear Outer tyre sidewall perished | |
| Advice | Unable to open side or rear doors at time of mot | |

CarCheck.co.uk page 6/20



ingress of dirt (6.1.7 (g) (ii))

Advice

Fail

Fail

MK60LFN

report date: 2024-03-28

MOT #13 2020-09-11 12:01 **MOT** test number 657210641165 Result × Failed Fail Hazard warning switch inoperative (4.4.2 (a) (ii)) **Advice** Nearside Rear tyre worn on outer edge **Advice** Offside Rear Outer tyre sidewall perished Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Nearside Front Side repeater missing lens (4.4.1 (a) (ii)) Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail **Advice** Offside Front Outer cv boot perished Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the

 MOT #12
 2019-09-09 14:56

 MOT test number
 805936570436

Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Minor Nearside Side repeater insecure (4.4.1 (c) (i))

Advice Rear Body component slightly loose door (6.2.1 (a) (i))

Unable to open side or rear doors at time of mot

Nearside Side repeater not working (4.4.1 (a) (ii))

Advice Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))

Advice Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))

CarCheck.co.uk page 7/20



report date: 2024-03-28

MOT #11 2019-08-27 13:55

MOT test number 420427026616

Result X Failed

Fail Nearside Body component damaged and likely to cause injury mirror body (6.2.1 (a) (i))

Advice Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Rear Body component slightly loose door (6.2.1 (a) (i))

Minor Nearside Side repeater insecure (4.4.1 (c) (i))

Advice Nearside Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

CarCheck.co.uk page 8/20



report date: 2024-03-28

MOT #10 2018-08-24 14:43

MOT test number 641016422101

✓ Passed Result **Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a)) Advice Nearside Rear lamp lens has slight damage Advice Some side marker lamps not working Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) Advice Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Offside Front Direction indicator slightly discoloured (4.4.3 (a)) Advice Advice Auxiliary drive belt in poor condition Advice Centre stop lamp not working

CarCheck.co.uk page 9/20



report date: 2024-03-28

MOT #9 2018-08-17 09:00

MOT test number 992041753666

Result X Failed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Some side marker lamps not working

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Headlamp are incorrectly positioned bulb insecure (4.1.4 (a))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Fail Nearside Side repeater missing (4.4.1 (a) (ii))

Fail Nearside Rear reflector missing (4.8.2 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Auxiliary drive belt in poor condition

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Centre stop lamp not working

Fail Headlamp aim not tested (4.1.2 (b))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Fail Offside Side repeater missing (4.4.1 (a) (ii))

Fail Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

Advice Nearside Rear lamp lens has slight damage

Fail Offside Front Position lamp not working (4.2.1 (a))

CarCheck.co.uk page 10/20



report date: 2024-03-28

MOT #8 2017-09-11 08:35

MOT test number 606593670725

Result ✓ Passed

MOT #7 2016-09-08 10:33

MOT test number 744904102416

Result

✓ Passed

MOT #6 2015-09-01 10:33

MOT test number 499074945287

Result
✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #5 2015-09-01 10:33

MOT test number 446484945206

Result X Failed

Pass with rectification Offside Headlamp aim too high (1.8)

Advice Parking brake lever has little reserve travel (3.1.6b)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #4 2014-09-09 13:28

MOT test number 448902954209

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 11/20



report date: 2024-03-28

MOT #3 2014-09-05 11:45

MOT test number 975608144248

Result X Failed

Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Nearside Rear fog lamp emits a light other than red (1.3.2e)

Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Nearside Front Electrical wiring insecure (1.9.2a)

MOT #2 2013-09-04 14:38

MOT test number 978337843233

Result \(\sqrt{Passed} \)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 12/20



Advice

MK60LFN

report date: 2024-03-28

MOT #1 2013-08-29 09:54

MOT test number 816661543239

Result × Failed Fail Nearside Headlamp not working on dipped beam (1.7.5a) Fail Nearside Rear Rear fog lamp emits a light other than red (1.3.2e) Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a) Fail Offside Rear Body has a sharp edge caused by damage (6.1.C.1) **Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7) Offside Headlamp not working on dipped beam (1.7.5a) Fail Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the Fail ingress of dirt etc (2.5.C.1a)

Front registration plate deteriorated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 13/20



report date: 2024-03-28

Tax & MOT check



Days left 338
MOT expiry date 19 April 2025

Full MOT history See MOT history

CarCheck.co.uk page 14/20



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 15/20



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 16/20



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full re | |
|---|---|
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | m.n.o |
| Current registration | NIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 17/20



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courts at info | |

Contact info

More info >

CarCheck.co.uk page 18/20



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 24 |
| First mileage registration | 2010-09-09 |
| Last registration | 2024-03-21 |
| Complete history | See info |



| Registration #1 | 2010-09-09 | 16 mi |
|------------------|------------|------------|
| Registration #2 | 2013-08-29 | 47.991 mi |
| Registration #3 | 2013-09-04 | 48.534 mi |
| Registration #4 | 2014-09-05 | 65.814 mi |
| Registration #5 | 2014-09-09 | 66.043 mi |
| Registration #6 | 2015-09-01 | 84.071 mi |
| Registration #7 | 2016-09-08 | 103.459 mi |
| Registration #8 | 2017-09-11 | 115.164 mi |
| Registration #9 | 2018-08-17 | 126.029 mi |
| Registration #10 | 2018-08-24 | 126.370 mi |
| Registration #11 | 2019-08-27 | 134.910 mi |
| Registration #12 | 2019-09-09 | 135.179 mi |
| Registration #13 | | 11,117 es |
| Registration #14 | | 77.777 es |
| Registration #15 | | 11,117 es |
| Registration #16 | | 77.777 es |
| Registration #17 | | 11,117 mi |
| Registration #18 | | 77.777 es |
| Registration #19 | | 11,117 es |
| Registration #20 | | 71.777 es |
| Registration #21 | | 71,777 es |
| Registration #22 | | 11.777 es |
| Registration #23 | | 11.777 es |
| Registration #24 | | D1 202 and |

More info >



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Additional information

| Fuel tank capacity | 105 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number | C007369 |

CarCheck.co.uk page 20/20