




report date: 2024-03-29

General information

Make	VOLVO
Model	V60
Colour	Grey
Year of manufacture	2018
Gearbox	8 speed automatic

Engine & fuel consumption

Power	250 BHP
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	43.7 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-12
Pictures	17
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-01-03
<b>MOT pass rate</b>	100 %
<b>MOT passed</b>	3
<b>Failed MOT tests</b>	0
<b>Total advice items</b>	11
<b>Total items failed</b>	0

**MOT #3** 2023-12-28 12:27**MOT test number** 825869798231**Result** Passed**Next expiry date** 2025-01-03

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt

**MOT #2** 2023-01-04 11:45**MOT test number** 144186865731**Result** Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Unable to fully inspect due to covers and shields



MOT #1	2021-10-08 09:35
MOT test number	311624346602
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
3 January 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	1
<b>MOT expiry date</b>	3 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>First licence fee (12 months)</b>	£ 645,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2018-10-24
Last registration	2023-12-28
Complete history	<a href="#">See info</a>



Registration #1	2018-10-24	10 mi
Registration #2	2021-10-08	28.289 mi
Registration #3	2023-05-22	29.277 mi
Registration #4	2023-05-22	29.277 mi
Registration #5	2023-05-22	29.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2040 mm
Height	1427 mm
Length	4761 mm
Wheel base	2872 mm
Max. allowed weight	2250 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	2841581