



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T SPORT
Colour	Black
Year of manufacture	2004
Top speed	140 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	192 Nm at 6.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.4 mpg
Consumption extra urban	42.1 mpg
Consumption combined	34.0 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-03
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-01
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	55
Total items failed	14

MOT #212023-08-14 14:10

MOT test number922672479493

Result✓ Passed

Next expiry date2024-09-01

- Minor

Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice

Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush. (5.3.4 (a) (i))
- Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Rear Tyre slightly damaged/cracking or perishing Both the rear tyres are cracked. (5.2.3 (d) (ii))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush. (5.3.4 (a) (i))
- Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #20**

2023-08-14 09:44

MOT test number

986793456953

Result

✗ Failed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush. (5.3.4 (a) (i))

Advice Rear Tyre slightly damaged/cracking or perishing Both the rear tyres are cracked. (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush. (5.3.4 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #19

2022-09-02 11:21

MOT test number

850693782617

Result

✓ Passed

MOT #18

2021-03-03 09:52

MOT test number

320953490366

Result

✓ Passed

MOT #17

2019-07-26 10:18

MOT test number

623540528328

Result

✓ Passed

Advice Front tyres wearing on edges, rear axle beam bushes wearing

**MOT #16** 2018-07-27 08:55**MOT test number** 381677538086**Result** ✓ Passed**Advice** Rear axle beam bushes wearing**MOT #15** 2017-07-29 08:14**MOT test number** 770630534540**Result** ✓ Passed**Advice** Offside Rear Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #14** 2016-07-29 08:51**MOT test number** 776285692839**Result** ✓ Passed**Advice** Front tyres wearing on edges**MOT #13** 2015-07-18 08:58**MOT test number** 165289295113**Result** ✓ Passed**Advice** Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #12** 2014-08-01 14:44**MOT test number** 248943514208**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Spare tyre flat
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Handbrake application uneven inspection required

MOT #11 2014-07-28 09:55**MOT test number** 428679004228**Result** ✗ Failed

- Notice** Handbrake application uneven inspection required
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Spare tyre flat
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2013-07-20 09:47**MOT test number** 679071103208**Result** ✓ Passed

**MOT #9** 2012-08-21 17:26**MOT test number** 899864532226**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Inner face of front brake discs corroding.**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2011-09-14 10:49**MOT test number** 437687951255**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2010-09-15 12:08**MOT test number** 252008850217**Result** ✓ Passed**MOT #6** 2009-08-20 12:25**MOT test number** 764912739255**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5** 2009-08-19 09:26**MOT test number** 361761339269**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2008-08-06 16:17**MOT test number** 811929218223**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2008-08-05 15:45**MOT test number** 933548318222**Result** ✗ Failed**Fail** Nearside Front brake disc has restricted free movement (3.5.1j)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc slightly scored (3.5.1h)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear brake disc excessively scored (3.5.1h)**Fail** Offside Rear brake disc has restricted free movement (3.5.1j)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #2	2007-09-03 11:21
MOT test number	132476847286
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2007-09-03 09:33
MOT test number	192126347267
Result	✗ Failed
Fail	Nearside Front brake disc excessively scored (3.5.1h)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front brake disc excessively scored (3.5.1h)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	RV54KVC
Plate since	2024-03-29
Current registration	RV54KVC
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-01
Last registration	2023-08-14
Complete history	See info



Registration #1	2004-09-01	12 mi
Registration #2	2007-09-03	43.750 mi
Registration #3	2007-09-03	43.750 mi
Registration #4	2008-08-05	54.868 mi
Registration #5	2008-08-06	54.868 mi
Registration #6	2009-08-19	64.498 mi
Registration #7	2009-08-20	64.498 mi
Registration #8	2010-09-15	72.185 mi
Registration #9	2011-09-14	79.927 mi
Registration #10	2012-08-21	85.342 mi
Registration #11	2013-07-20	95.255 mi
Registration #12	2014-07-28	116.454 mi
Registration #13	2015-08-20	125.277 mi
Registration #14	2016-08-20	135.277 mi
Registration #15	2017-08-20	145.277 mi
Registration #16	2018-08-20	155.277 mi
Registration #17	2019-08-20	165.277 mi
Registration #18	2020-08-20	175.277 mi
Registration #19	2021-08-20	185.277 mi
Registration #20	2022-08-20	195.277 mi
Registration #21	2023-08-20	205.277 mi
Registration #22	2024-08-20	215.277 mi
Registration #23	2025-08-20	225.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1255 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number

2ZZ0141486