



General information

Make	VOLKSWAGEN
Model	SHARAN
Colour	Blue
Year of manufacture	2002
Gearbox	-

Engine & fuel consumption

Engine capacity	1.896 cc
Fuel type	Diesel
CO2 emission	173 g/km
CO2 label	H





MOT history

MOT expiry date	2020-12-19
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	33
Total items failed	4

MOT #17 2019-12-09 13:54

MOT test number 781885575279

Result ✓ Passed

Next expiry date 2020-12-19

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16 2018-12-20 12:15

MOT test number 672251472013

Result ✓ Passed

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15** 2017-12-16 16:06**MOT test number** 213827893821**Result** ✓ Passed**Advice** Front Macpherson strut has slight movement at the upper attachment both (2.5.A.1c)**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Advice** Front Front suspension has slight play in a track control arm inner bush both inner (2.5.B.2b)**MOT #14** 2016-12-05 11:42**MOT test number** 214121853045**Result** ✓ Passed**Advice** Offside Front Steering arm damaged but serviceable (2.2.C.1d)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Steering arm damaged but serviceable (2.2.C.1d)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #13** 2015-12-09 12:25**MOT test number** 586318150634**Result** ✓ Passed**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Vehicle structure has slight damage (6.1.A.1)**Advice** Nearside Front Vehicle structure has slight damage (6.1.A.1)**Advice** Body has slight corrosion (6.1.B.2)**MOT #12** 2014-11-29 09:47**MOT test number** 699643734395**Result** ✓ Passed

**MOT #11** 2013-11-30 09:41**MOT test number** 255634033399**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #10** 2012-11-27 17:01**MOT test number** 919782732314**Result** ✓ Passed**MOT #9** 2012-11-19 11:22**MOT test number** 186394722352**Result** ✗ Failed**Fail** Offside Front Ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Nearside Front Ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #8** 2011-12-10 10:36**MOT test number** 199324941372**Result** ✓ Passed**MOT #7** 2010-11-27 11:19**MOT test number** 121631230355**Result** ✓ Passed**MOT #6** 2009-11-26 14:23**MOT test number** 452290039428**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #5** 2008-12-03 15:08**MOT test number** 363018138340**Result** ✓ Passed

Advice Nearside Front Suspension component mounting prescribed area is distorted but not considered excessive (2.4.A.3)

Advice Offside Front Suspension component mounting prescribed area is distorted but not considered excessive (2.4.A.3)

MOT #4 2007-12-11 09:54**MOT test number** 410685947321**Result** ✓ Passed

Notice Nearside rear brake binding slightly

Notice Offside rear caliper handbrake lever not fully returning

MOT #3 2006-12-12 12:00**MOT test number** 223496646376**Result** ✗ Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Offside outer track rod end joint cover split/missing

Pass with rectification Offside Front Headlamp aim too low (1.8)



MOT #2	2006-12-12 12:00
MOT test number	421386546465
Result	✓ Passed
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
Notice	Offside outer track rod end joint cover split/missing
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2006-05-15 11:40
MOT test number	891495036151
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
24 September 2020

✕
MOT

Expired:
19 December 2020

Tax status	Expired at 24 September
Days left	1313 days too late
MOT expiry date	19 December 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2002-07-08
Last registration	2019-12-09
Complete history	See info



Registration #1	2002-07-08	23 mi
Registration #2	2006-05-15	72.831 mi
Registration #3	2006-12-12	96.187 mi
Registration #4	2007-12-11	110.289 mi
Registration #5	2008-12-03	122.520 mi
Registration #6	2009-11-26	131.856 mi
Registration #7	2010-11-27	142.276 mi
Registration #8	2011-12-10	152.143 mi
Registration #9	2012-11-19	159.481 mi
Registration #10	2013-11-19	166.819 mi
Registration #11	2014-11-19	174.157 mi
Registration #12	2015-11-19	181.495 mi
Registration #13	2016-11-19	188.833 mi
Registration #14	2017-11-19	196.171 mi
Registration #15	2018-11-19	203.509 mi
Registration #16	2019-11-19	210.847 mi
Registration #17	2019-12-09	218.185 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN