



report date: 2024-03-28

General information

Make	KIA
Model	RIO CRDI 1 AIR ECODYNAMICS
Colour	White
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	15.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	170 Nm at 1.500 rpm
Engine capacity	1.120 cc
Cylinders	3
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-06-08
Pictures	54
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-23
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	20
Total items failed	3

MOT #11	2023-06-23 15:42
MOT test number	712023891438
Result	✓ Passed
Next expiry date	2024-06-23

MOT #10	2022-06-17 15:40
MOT test number	671951018273
Result	✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #9	2021-06-24 12:11
MOT test number	989604293385
Result	✓ Passed

**MOT #8** 2020-11-25 12:39**MOT test number** 834989146758**Result** ✓ Passed**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #7** 2020-11-25 11:19**MOT test number** 271110316372**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Headlamp aim not tested (4.1.2 (b))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #6** 2019-11-27 10:39**MOT test number** 696849531069**Result** ✓ Passed

**MOT #5** 2018-11-23 13:50**MOT test number** 498126803869**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2017-11-24 13:29**MOT test number** 327558713357**Result** ✓ Passed

- Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Outer tyre has a cut in the sidewall, not deep enough to reach chords

MOT #3 2016-12-05 16:54**MOT test number** 567821444674**Result** ✓ Passed**MOT #2** 2015-11-05 15:50**MOT test number** 482079501172**Result** ✓ Passed**MOT #1** 2015-02-04 11:29**MOT test number** 726075135037**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SY12NYF
Plate since	2019-09-29
Current registration	SY12NYF
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-28
Last registration	2023-06-23
Complete history	See info



Registration #1	2012-03-28	10 mi
Registration #2	2015-02-04	19.193 mi
Registration #3	2015-11-05	19.602 mi
Registration #4	2016-12-05	34.656 mi
Registration #5	2017-11-24	44.281 mi
Registration #6	2018-11-23	54.068 mi
Registration #7	2019-11-27	62.622 mi
Registration #8	2020-06-23	71.277 mi
Registration #9	2021-06-23	80.277 mi
Registration #10	2022-06-23	89.277 mi
Registration #11	2023-06-23	98.277 mi
Registration #12	2024-03-28	107.277 mi
Registration #13	2024-03-28	116.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1293 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D3FACH309695