



General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI STARTLINE
Colour	Black
Year of manufacture	2017
Top speed	107 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-24
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #6	2023-11-24 09:49
MOT test number	194001019416
Result	✓ Passed
Next expiry date	2024-11-24

MOT #5	2022-11-25 16:40
MOT test number	999772979901
Result	✓ Passed
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both anti-roll bar mounting bushes have slight play/wear (5.3.4 (a) (i))
Advice	Bulb warning light on dash

MOT #4	2022-11-25 10:04
MOT test number	489858491314
Result	✗ Failed
Fail	Offside Front Direction indicator light intensity significantly reduced not fitted properly (4.4.3 (a))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both anti-roll bar mounting bushes have slight play/wear (5.3.4 (a) (i))
Fail	Front Position lamp not working both (4.2.1 (a) (ii))
Advice	Bulb warning light on dash

**MOT #3** 2021-09-07 12:54**MOT test number** 471201480564**Result** ✓ Passed**MOT #2** 2020-10-06 12:06**MOT test number** 234963590845**Result** ✓ Passed**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Engine oil low level**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #1** 2020-10-06 12:06**MOT test number** 686313853340**Result** ✗ Failed**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Engine oil low level



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
24 November 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-29
Last registration	2023-11-24
Complete history	See info



Registration #1	2017-09-29	10 mi
Registration #2	2020-10-06	80.175 mi
Registration #3	2020-10-06	80.175 mi
Registration #4	2020-10-06	80.175 mi
Registration #5	2020-10-06	80.175 mi
Registration #6	2020-10-06	80.175 mi
Registration #7	2020-10-06	80.175 mi
Registration #8	2020-10-06	80.175 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Wheel base	3006 mm
Kerb weight	1565 kg
Max. allowed weight	2299 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	2
Number of axles	2
Engine number	DFSD223023