



report date: 2024-03-28

General information

Make	KIA
Model	SEDONA LS
Colour	Red
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-20
Pictures	17
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #19** 2022-12-21 18:02**MOT test number** 190958281883**Result** ✓ Passed**Next expiry date** 2024-01-13**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #18** 2022-12-20 12:05**MOT test number** 727181115605**Result** ✗ Failed**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #17** 2022-01-14 10:07**MOT test number** 689270461771**Result** ✓ Passed**Advice** Under body slightly corroded

**MOT #16**

2022-01-12 15:06

MOT test number

470232736633

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**Advice** Fuel filler pipe clip snapped**Fail** Windscreen wiper does not clear the windscreen effectively both front (3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin both rear (1.1.13 (a) (ii))**Advice** Under body slightly corroded**MOT #15**

2020-09-23 10:16

MOT test number

317835629196

Result**✓ Passed****Advice** Oil leak from steering rack**Advice** Offside Rear Anti-roll bar damaged but not seriously weakened slight play (5.3.3 (b) (i))

**MOT #14**

2020-09-14 13:36

MOT test number

818295645132

Result**✗ Failed**

Fail Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Brake pipe excessively corroded front to rear (1.1.11 (c))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Offside Front Brake pipe excessively corroded to ABS pump (1.1.11 (c))

Fail Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Advice Oil leak from steering rack

Advice Offside Rear Anti-roll bar damaged but not seriously weakened slight play (5.3.3 (b) (i))

MOT #13

2019-09-06 13:22

MOT test number

949351604962

Result**✓ Passed**

Advice Offside Front rack end has slight play

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2019-09-04 09:29

MOT test number

287686698503

Result**✗ Failed**

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front rack end has slight play

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #11

2018-09-14 09:04

MOT test number

385193051696

Result**✓ Passed**

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2017-09-14 10:12

MOT test number

655355284326

Result**✓ Passed**

Advice Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #9

2016-09-14 15:44

MOT test number

258423743112

Result**✓ Passed**

Advice Rear wiper blade

**MOT #8** 2016-09-07 10:40**MOT test number** 175160096678**Result** ✗ Failed**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Rear wiper blade**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #7** 2015-09-07 09:41**MOT test number** 385387072067**Result** ✓ Passed**Advice** Rear wiper blade split**MOT #6** 2014-09-04 10:36**MOT test number** 978937944204**Result** ✓ Passed**Notice** Advise n/s/r slight brake bind**MOT #5** 2013-09-05 15:38**MOT test number** 728898843267**Result** ✓ Passed**MOT #4** 2012-08-10 13:04**MOT test number** 848433022208**Result** ✓ Passed



MOT #3	2011-08-11 12:14
MOT test number	858683221232
Result	✓ Passed
MOT #2	2010-08-13 16:34
MOT test number	892985220272
Result	✓ Passed
MOT #1	2009-08-14 11:06
MOT test number	263756429286
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	NU56ATN
Plate since	2019-09-28
Current registration	NU56ATN
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-07
Last registration	2022-12-21
Complete history	See info



Registration #1	2006-09-07	17 mi
Registration #2	2009-08-14	15.417 mi
Registration #3	2010-08-13	20.781 mi
Registration #4	2011-08-11	27.159 mi
Registration #5	2012-08-10	33.199 mi
Registration #6	2013-09-05	41.144 mi
Registration #7	2014-09-04	51.564 mi
Registration #8	2015-09-07	65.709 mi
Registration #9	2016-09-07	101.997 mi
Registration #10	2016-09-14	75.683 mi
Registration #11	2017-09-14	82.550 mi
Registration #12	2018-09-14	91.222 mi
Registration #13	2019-09-14	101.222 mi
Registration #14	2020-09-14	111.222 mi
Registration #15	2021-09-14	121.222 mi
Registration #16	2022-09-14	131.222 mi
Registration #17	2023-09-14	141.222 mi
Registration #18	2024-09-14	151.222 mi
Registration #19	2025-09-14	161.222 mi
Registration #20	2026-09-14	171.222 mi
Registration #21	2027-09-14	181.222 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2168 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3751445