



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO F3500 L2H1 CRC CDTi
Colour	White
Year of manufacture	2014
Top speed	90 mph
0 - 60 mph	14.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	34.4 mpg
CO2 emission	213 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-14
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	18
Total items failed	18

MOT #11	2024-04-05 14:43
MOT test number	922397140740
Result	✓ Passed
Next expiry date	2025-04-04
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10	2023-02-14 15:18
MOT test number	644587347668
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2022-04-21 13:04
MOT test number	835874966905
Result	✓ Passed

MOT #8	2020-10-30 15:09
MOT test number	909334447586
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Nearside Front Outer Seat belt slightly damaged (7.1.2 (b) (i))

**MOT #7**

2020-10-22 15:33

MOT test number

582870261445

Result**✗ Failed**

- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Brake pipe likely to become detached or damaged (1.1.11 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Fail** Nearside Front Seat belt not functioning as intended centre (7.1.2 (c))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Nail in tyre
- Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Nearside Front Outer Seat belt slightly damaged (7.1.2 (b) (i))

MOT #6

2019-04-30 14:44

MOT test number

468579350928

Result**✓ Passed**

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #5** 2019-04-30 13:49**MOT test number** 635677066952**Result** ✗ Failed**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Front Windscreen washer not working (3.5 (a))**Fail** Central Front Seat belt retracting mechanism defective (7.1.2 (e))**MOT #4** 2018-04-23 10:32**MOT test number** 492843232858**Result** ✓ Passed**Advice** Oil leak**MOT #3** 2018-04-17 16:29**MOT test number** 638070364227**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Oil leak**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Rear parking (secondary) brakes imbalanced (3.7.B.6b)**MOT #2** 2017-04-10 10:32**MOT test number** 926105075104**Result** ✓ Passed**Advice** Offside Rear Nail in tyre



MOT #1	2017-03-29 10:52
MOT test number	697145266057
Result	✗ Failed
Advice	Offside Rear Nail in tyre
Fail	Fuel system component leaking filter (7.2.3)
Fail	Parking brake: efficiency below requirements (3.7.B.7)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-26
Last registration	2024-04-05
Complete history	See info



Registration #1	2014-03-26	28 mi
Registration #2	2017-03-29	38.107 mi
Registration #3	2017-04-10	38.108 mi
Registration #4	2018-04-17	49.446 mi
Registration #5	2018-04-23	49.446 mi
Registration #6	2019-04-30	58.786 mi
Registration #7	2019-04-30	58.788 mi
Registration #8	2019-05-01	58.788 mi
Registration #9	2019-05-01	58.788 mi
Registration #10	2019-05-01	58.788 mi
Registration #11	2019-05-01	58.788 mi
Registration #12	2019-05-01	58.788 mi
Registration #13	2019-05-01	58.788 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2301 mm
Length	5643 mm
Kerb weight	1887 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	M9T -C082935 LWL