





report date: 2024-03-29

General information

Make	LEXUS
Model	IS 300H LUXURY
Colour	Grey
Year of manufacture	2014
Top speed	125 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	178 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.493 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-19

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



SC14VHT

report date: 2024-03-29

MOT history

MOT expiry date	2025-01-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	10
Total items failed	3

MOT #10	2023-12-13 16:55
MOT test number	873504436077
Result	✓ Passed
Next expiry date	2025-01-02

MOT #9	2023-12-11 12:05
MOT test number	349559651757

Result × Failed

MAJOR Nearside Front Headlamp aim too high (4.1.2 (a))

MAJOR Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MAJOR Nearside Front Upper Suspension rod ball joint dust cover no longer prevents the ingress of dirt roll bar link rubber split (5.3.4 (b) (ii))

MAJOR Offside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

MAJOR Offside Front Upper Suspension rod ball joint dust cover no longer prevents the ingress of dirt roll bar link rubber split (5.3.4 (b) (ii))

MOT #8	2022-12-28 16:33
MOT test number	705551278549
Result	✓ Passed

CarCheck.co.uk page 3/12



SC14VHT

report date: 2024-03-29

MOT test number

Result

Pass with rectification
Pass with rectification
Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Pass with rectification
Inoperative (5.2.3 (h))

 MOT #6
 2022-01-03 10:06

 MOT test number
 481920644622

 Result
 ✓ Passed

MOT #5

MOT test number

759314678446

Result

Pass with rectification (h))

Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3

 MOT #4
 2020-12-22 12:05

 MOT test number
 864337742921

 Result
 ✓ Passed

 MOT #3
 2019-06-06 15:27

 MOT test number
 106752810345

 Result
 ✓ Passed

Advice Nearside rear tyre wearing inner edge

CarCheck.co.uk page 4/12



Advice

SC14VHT report date: 2024-03-29

MOT test number

Result

Advice
Unable to fully inspect the nearside rear seatbelt due to child seat fitted

Advice
Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2017-06-22 16:14
MOT test number	119272728029
Result	✓ Passed

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e union matery	
For how long did the current and previous owner(s) have this LEXUS? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

manus .	

	More info >
Plate changes	
Coo in this chook if this I EVIIC had different women or plates	
See in this check if this LEXUS had different number plates.	
Number of plates	
Current registration	UK NEW
Fiate since	
Current registration	UK UK
Finite since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-06-30
Last registration	2023-12-13
Complete history	See info



Registration #1	2014-06-30	27 mi
Registration #2	2017-06-22	39.688 mi
Registration #3	2018-06-04	50.330 mi
Registration #4	2019-06-06	60.668 mi
Registration #5	2020-12-22	74.055 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12

Number of axles 2

Engine number 2AR1005509