



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI
Colour	Black
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-30
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	24
Total items failed	12

MOT #20 2024-03-11 09:30

MOT test number 458730648490

Result ✓ Passed

Next expiry date 2025-03-30

- Advice** Rear both spring carriers corrosion
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front headlamp lens misting
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19 2023-03-31 12:11

MOT test number 162309983098

Result ✓ Passed

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18**

2023-03-28 13:51

MOT test number

884846731467

Result**✗ Failed**

Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Nearside Front Brake pipe inadequately clipped or supported (1.1.11 (d) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Offside Rear Suspension component pin or bush excessively worn TRAILING ARM BUSH (5.3.4 (a) (i))

MOT #17

2022-03-05 09:27

MOT test number

328319640239

Result**✓ Passed**

Advice Offside Play in steering rack inner joint(s)

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16

2021-03-25 08:05

MOT test number

395106161909

Result**✓ Passed**

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2021-03-23 08:30**MOT test number** 860807233489**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Rear Road wheel fixing loose (5.2.1 (a) (i))**MOT #14** 2020-08-06 14:52**MOT test number** 616532515897**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2020-08-06 14:00**MOT test number** 164330792522**Result** ✗ Failed**Fail** Front Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2019-08-31 08:10**MOT test number** 691893838618**Result** ✓ Passed

**MOT #11** 2019-08-30 08:29**MOT test number** 351876011590**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-08-31 16:22**MOT test number** 277376455798**Result** ✓ Passed**Advice** Brake pad(s) wearing thin Rear (1.1.13 (a) (ii))**MOT #9** 2018-08-31 07:40**MOT test number** 894390411069**Result** ✗ Failed**Advice** Brake pad(s) wearing thin Rear (1.1.13 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-09-01 09:06**MOT test number** 916995703812**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit Both (4.1.E.1)**MOT #7** 2016-08-11 10:32**MOT test number** 807535037044**Result** ✓ Passed**MOT #6** 2015-08-29 09:58**MOT test number** 883843821823**Result** ✓ Passed



MOT #5	2014-08-12 14:39
MOT test number	347494524431
Result	✓ Passed
MOT #4	2013-08-20 09:31
MOT test number	496582433235
Result	✓ Passed
MOT #3	2012-08-17 09:32
MOT test number	259140932263
Result	✓ Passed
MOT #2	2011-08-31 16:13
MOT test number	706463241221
Result	✓ Passed
<div>NoticeTraction control light on</div>	
MOT #1	2010-08-23 10:48
MOT test number	303745130433
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 March 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	30 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KP07V
Plate since	2024-03-28
Current registration	 KP07V
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-04-24
Last registration	2024-03-11
Complete history	See info



Registration #1	2007-04-24	18 mi
Registration #2	2010-08-23	19.382 mi
Registration #3	2011-08-31	22.866 mi
Registration #4	2012-08-17	26.155 mi
Registration #5	2013-08-20	29.303 mi
Registration #6	2014-08-12	32.765 mi
Registration #7	2015-08-29	36.242 mi
Registration #8	2016-08-11	39.665 mi
Registration #9	2017-09-01	42.595 mi
Registration #10	2018-08-31	45.681 mi
Registration #11	2018-08-31	45.681 mi
Registration #12	2019-05-29	50.277 mi
Registration #13	2019-05-29	50.277 mi
Registration #14	2019-05-29	50.277 mi
Registration #15	2019-05-29	50.277 mi
Registration #16	2019-05-29	50.277 mi
Registration #17	2019-05-29	50.277 mi
Registration #18	2019-05-29	50.277 mi
Registration #19	2019-05-29	50.277 mi
Registration #20	2019-05-29	50.277 mi
Registration #21	2019-05-29	50.277 mi
Registration #22	2024-03-11	50.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1570 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Engine number	BMM 122233