



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI ACTIVE BLUE DRIVE
Colour	White
Year of manufacture	2013
Top speed	125 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-06
Pictures	32
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-23
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	16
Total items failed	9

MOT #12	2023-11-24 08:40
MOT test number	191132686494
Result	✓ Passed
Next expiry date	2024-11-23
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge also nail inner shoulder (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-11-15 15:53
MOT test number	167462564616
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Vehicle undersealed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2022-11-11 12:03

MOT test number

947931557983

Result**✗ Failed****Advice**

Rear brake hose ferrules corroded

Fail

Steering column flexible coupling is excessively deteriorated (2.2.2 (c))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Slight underbody corrosion on rear axle

Advice

Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2022-05-12 15:50

MOT test number

690633849473

Result**✓ Passed****MOT #8**

2022-05-12 10:03

MOT test number

910436046483

Result**✗ Failed****Fail**

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail

Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail

Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #7

2021-05-25 15:46

MOT test number

679732687753

Result**✓ Passed**

**MOT #6** 2020-10-14 15:50**MOT test number** 173073895719**Result** ✓ Passed**Advice** Both front tyres wearing on edges**MOT #5** 2020-10-14 13:50**MOT test number** 314425935642**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Both front tyres wearing on edges**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #4** 2019-06-26 08:59**MOT test number** 955316180024**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-05-31 10:58**MOT test number** 289305756230**Result** ✓ Passed**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))



MOT #2	2018-05-31 10:58
MOT test number	622143469276
Result	✗ Failed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Pass with rectification	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #1	2017-06-19 08:26
MOT test number	420602392895
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
23 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	23 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	SD63ULJ
Plate since	2019-03-29
Current registration	SD63ULJ
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-10-19
Last registration	2023-11-24
Complete history	See info



Registration #1	2013-10-19	26 mi
Registration #2	2017-06-19	27.237 mi
Registration #3	2018-05-31	31.164 mi
Registration #4	2018-05-31	31.164 mi
Registration #5	2019-06-26	36.302 mi
Registration #6	2020-10-14	45.210 mi
Registration #7	2020-10-14	57.191 mi
Registration #8	2023-11-24	58.277 mi
Registration #9	2023-11-24	58.277 mi
Registration #10	2023-11-24	58.277 mi
Registration #11	2023-11-24	58.277 mi
Registration #12	2023-11-24	58.277 mi
Registration #13	2023-11-24	58.277 mi
Registration #14	2023-11-24	58.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4FDDU366713