





report date: 2024-03-29

General information

Make	MINI
Model	ONE
Colour	Red
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 4

Date 2023-03-22

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 3

Date 2022-11-14

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk


Entry 2

Date 2022-10-03

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-06-06

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	~		
10/1/	1	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2025-04-16
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	21
Total items failed	0

MOT #10	2024-04-04 21:26
MOT test number	708582168157
Result	✓ Passed
Next expiry date	2025-04-16
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lam (b) (i))	ps or light sources (4.7.1

MOT #9	2023-04-17 16:03
MOT test number	790931478084
Result	✓ Passed

MOT #8	2022-06-09 09:01
MOT test number	779497147522
Result	✓ Passed

MOT #7	2021-06-16 14:51
MOT test number	830085701781
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2021-04-01 09:51 368963255067 **MOT** test number Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge worn shoulder (5.2.3 (e)) Offside Front Tyre slightly damaged/cracking or perishing sidewall cut/old (5.2.3 (d) (ii)) Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge worn shoulder (5.2.3 (e)) Advice Nearside Front Tyre slightly damaged/cracking or perishing sidewall perished/old (5.2.3 (d) (ii)) Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Advice Engine, under tray and floor covers fitted

MOT #5	2020-03-25 16:42
MOT test number	155839938348
Result	✓ Passed
Advice Covers fitted	

MOT #4	2019-03-27 10:43
MOT test	number 347703178727
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing sidewall heavily perished (5.2.3 (d) (ii))
Advice (ii))	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion (1.1.14 (a)
Advice	Offside Rear Tyre slightly damaged/cracking or perishing sidewall heavily perished (5.2.3 (d) (ii))
Advice	Under trays and floor covers fitted
Advice (ii))	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corrosion (1.1.14 (a)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2018-02-09 17:46 **MOT test number** 811456660650 Result ✓ Passed **Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Plastic engine, under tray and floor covers fitted Advice Advice Offside Rear Tyre side wall perished. Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Rear Tyre side wall perished

MOT #2		2016-11-12 10:43
MOT test	number	143166404711
Result		✓ Passed
Advice	Under trays fitted preventing inspection of some under body parts	
Advice	Engine covers fitted preventing inspection of some under bonnet parts	

MOT #1	2015-10-29 17:34
MOT test number	578995426265
Result	√ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I	
HARMAN AND AND AND AND AND AND AND AND AND A	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NK NAME OF THE PROPERTY OF THE
Plate since	
Current registration	UK SIES
Plate since	

CarCheck.co.uk page 9/12



NA62ZDL report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-23
Last registration	2024-04-04
Complete history	See info



Registration #1	2012-11-23	23 mi
Registration #2	2015-10-29	12.625 mi
Registration #3	2016-11-12	17.413 mi
Registration #4	2018-02-09	23.848 mi
Registration #5	2019-03-27	29.502 mi
Registration #6	2020-03-25	35.037 mi
Registration #7	2021-04-01	36.474 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA024J283