





General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | IX35 CRDI SE |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 108 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 114 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 1.250 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |







Internet history

| Entry 2 | |
|---------------|--------------------|
| Date | 2021-07-12 |
| Pictures | 32 |
| Listing price | <u>View report</u> |



source: cargurus.co.uk

| Entry 1 | |
|---------|--|
|---------|--|

Date

Pictures

Listing price

2021-07-10 32

View report







source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-12 |
|--------------------|------------|
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 3 |

| MOT #9 | 2023-08-09 14:39 |
|--|------------------|
| MOT test number | 207061381262 |
| Result | 🗸 Passed |
| Next expiry date | 2024-08-12 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge 1.96mm (5.2.3 (e)) |) |
| Advice Offside Front Tyre worn close to legal limit/worn on edge 2.56mm (5.2.3 (e)) | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |

MOT #82023-08-09 09:37MOT test number741527161534Result× FailedFailOffside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))AdviceOffside Front Tyre worn close to legal limit/worn on edge 2.56mm (5.2.3 (e))AdviceOil leak, but not excessive (8.4.1 (a) (i))AdviceNearside Front Tyre worn close to legal limit/worn on edge 1.96mm (5.2.3 (e))

| MOT #7 | 2022-07-29 14:12 |
|--|------------------|
| MOT test number | 470604211324 |
| Result | ✓ Passed |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |





| MOT #6 | 2021-07-14 15:36 |
|-----------------|------------------|
| MOT test number | 518926548686 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2020-08-13 10:14 |
| MOT test number | 441437836754 |
| Result | ✓ Passed |
| | |

| MOT #4 | 2020-08-13 08:52 |
|---|------------------|
| MOT test number | 833455821870 |
| Result | 🗙 Failed |
| Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) | |
| Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |

| MOT #3 | 2019-03-23 10:29 |
|-----------------|------------------|
| MOT test number | 730184323175 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2018-04-04 09:15 |
| MOT test number | 423188237916 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2017-04-13 15:38 |
| MOT test number | 449939856014 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | мот |
|-------------------------|----------------------------|
| Tax due: 1 July 2024 | Expires: 12 August 2024 |
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 12 August 2024 |
| Full MOT history | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | ASMPL |
| Date | |
| Category | AMPL |
| Туре | |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| 1000000 | |
|--|-------------|
| ****** | |
| ******** | |
| | |
| 1000000 | |
| ******** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 12 |
| First mileage registration | 2014-07-14 |
| Last registration | 2023-08-09 |
| Complete history | <u>See info</u> |



| Registration #1 | 2014-07-14 | 12 mi |
|------------------------------------|------------|---|
| Registration #2 | 2017-04-13 | 31.541 mi |
| Registration #3 | 2018-04-04 | 36.309 mi |
| Registration #4 | 2019-03-23 | 53.666 mi |
| Registration #5 | 2020-08-13 | 72.505 mi |
| Registration #6 | 2020-08-13 | 72.505 mi |
| | | |
| Registration #7 | | 11.777 mi |
| Registration #7 Registration #8 | | 00.000 est |
| - | | 00.000 ees 00.000 ees 00.000 ees |
| Registration #8 | | 00.000 est 0.000 est 00.000 est 00.000 est |
| Registration #8 Registration #9 | | 00.000 460 0.000 460 00.000 460 00.000 460 00.000 460 |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 88% |
| Pedestrian | 54% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1820 mm |
| Height | 1665 mm |
| Length | 4410 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1537 kg |
| Max. allowed weight | 1940 kg |
| Additional information | |
| Fuel tank capacity | 58 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | D4FDEZ258681 |