



LJIIDDF


report date: 2024-03-28

General information

Make	MINI
Model	MINI (R58) COOPER D
Colour	Blue
Year of manufacture	2011
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-01
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-12-02
<b>MOT pass rate</b>	80 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	30
<b>Total items failed</b>	4

**MOT #15** 2023-11-15 15:13**MOT test number** 346123006173**Result** ✓ Passed**Next expiry date** 2024-12-02

- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-11-04 18:00**MOT test number** 870576250374**Result** ✓ Passed

- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2021-12-03 08:55**MOT test number** 464167821834**Result** ✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Under tray fitted

**MOT #12** 2021-01-28 10:08**MOT test number** 848038453812**Result** ✓ Passed**MOT #11** 2020-01-31 09:28**MOT test number** 204725559409**Result** ✓ Passed**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Tpms light on**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Front Upper strut rubbers splitting**MOT #10** 2019-01-14 16:03**MOT test number** 702684420258**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Both front upper strut rubbers split

**MOT #9** 2019-01-14 10:12**MOT test number** 950413510444**Result** ✗ Failed**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Brake pad(s) wearing thin o/s/r and o/s/f (1.1.13 (a) (ii))**MAJOR** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Both front upper strut rubbers split**MAJOR** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**MOT #8** 2018-01-10 16:44**MOT test number** 114978924773**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2017-01-19 11:34**MOT test number** 543409412224**Result** ✓ Passed

**MOT #6** 2017-01-16 12:25**MOT test number** 859971104602**Result** ✗ Failed

- Fail** Offside Headlamp aim too high (1.8)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #5** 2016-02-02 12:10**MOT test number** 954900202416**Result** ✓ Passed

- Advice** Plastic covers fitted to underside and outer body sills.

**MOT #4** 2015-09-14 08:59**MOT test number** 917933806114**Result** ✓ Passed**MOT #3** 2015-02-18 10:33**MOT test number** 177279845426**Result** ✓ Passed**MOT #2** 2014-02-04 12:11**MOT test number** 388745734056**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1	2014-02-04 12:11
MOT test number	627855334076
Result	✗ Failed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
2 December 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	2 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>LJ11DDF</b>
Plate since	2019-09-28
Current registration	<b>LJ11DDF</b>
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-01
Last registration	2023-11-15
Complete history	<a href="#">See info</a>



Registration #1	2011-03-01	12 mi
Registration #2	2014-02-04	31.850 mi
Registration #3	2015-02-18	44.972 mi
Registration #4	2015-09-14	53.267 mi
Registration #5	2016-02-02	53.305 mi
Registration #6	2017-01-16	66.287 mi
Registration #7	2017-01-19	66.374 mi
Registration #8	2018-01-10	81.477 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	70757967