



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C30 D3 ES |
| Colour | Black |
| Year of manufacture | 2011 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 350 Nm at 1.500 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 134 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-07-09 |
| Pictures | 26 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-22 |
| MOT pass rate | 71 % |
| MOT passed | 10 |
| Failed MOT tests | 4 |
| Total advice items | 32 |
| Total items failed | 4 |

| | |
|------------------|---|
| MOT #14 | 2023-10-23 14:07 |
| MOT test number | 421802973279 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-22 |
| Advice | All direction indicators slightly discoloured Both Rear (4.4.3 (a)) |
| Minor | Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Minor | Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |



MOT #13

2022-10-21 16:02

MOT test number

363472362998

Result

✓ Passed

- Advice

Under trays fitted
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front head light dipped beam slight colour difference and flickering
- Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor

Nearside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2022-10-21 15:48

MOT test number

363297049296

Result**✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front head light dipped beam slight colour difference and flickering
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Under trays fitted

MOT #11

2021-09-29 19:28

MOT test number

775442939675

Result**✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10

2020-10-07 12:23

MOT test number

288366227549

Result**✓ Passed**

**MOT #9** 2020-10-07 12:23**MOT test number** 232904260354**Result** ✗ Failed**Pass with rectification** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2019-10-10 18:57**MOT test number** 411142173202**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-10-17 21:16**MOT test number** 621527154942**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2018-10-17 21:16**MOT test number** 173443090717**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #5** 2017-10-13 15:11**MOT test number** 657523523899**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #4 | 2017-10-13 11:39 |
| MOT test number | 159065272487 |
| Result | ✗ Failed |
| Fail | Nearside Front coil spring broken (2.4.C.1a) |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) |

| | |
|-----------------|------------------|
| MOT #3 | 2016-10-19 08:19 |
| MOT test number | 209859962929 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #2 | 2015-11-18 11:09 |
| MOT test number | 761273111865 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2014-12-02 12:20 |
| MOT test number | 519626434387 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 22 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2011-12-02 |
| Last registration | 2023-10-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-12-02 | 7 mi |
| Registration #2 | 2014-12-02 | 30.866 mi |
| Registration #3 | 2015-11-18 | 42.108 mi |
| Registration #4 | 2016-10-19 | 51.878 mi |
| Registration #5 | 2017-10-13 | 62.395 mi |
| Registration #6 | 2017-10-13 | 62.315 mi |
| Registration #7 | 2018-10-17 | 75.277 mi |
| Registration #8 | 2018-10-17 | 75.277 mi |
| Registration #9 | 2019-10-23 | 75.277 mi |
| Registration #10 | 2019-10-23 | 75.277 mi |
| Registration #11 | 2019-10-23 | 75.277 mi |
| Registration #12 | 2019-10-23 | 75.277 mi |
| Registration #13 | 2019-10-23 | 75.277 mi |
| Registration #14 | 2019-10-23 | 75.277 mi |
| Registration #15 | 2019-10-23 | 75.277 mi |
| Registration #16 | 2019-10-23 | 75.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1504 kg |
| Max. allowed weight | 2020 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1012435 |