



report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Red
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2021-02-19
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	26
Total items failed	19

MOT #12	2020-02-20 15:11
MOT test number	418308591490
Result	✓ Passed
Next expiry date	2021-02-19
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11	2020-02-20 15:11
MOT test number	587890369755
Result	✗ Failed
Pass with rectification	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #10**

2020-02-12 12:39

MOT test number

880653731508

Result**✗ Failed**

- Fail** Nearside Front Electrical wiring for braking components extremely deteriorated Brake pad sensor (4.11 (b) (iii))
- Fail** Offside Rear Seat belt retracting mechanism defective (7.1.2 (e))
- Fail** Offside Front Headlamp insecure (4.1.1 (c))
- Advice** Engine sump corroded, corrosion underneath various location
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Rear exhaust box corroded and exhaust shield not secured
- Advice** Offside Front Nail in tyre
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9

2019-11-01 11:27

MOT test number

488303270951

Result**✓ Passed**

- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp x2 (4.2.3 (c))
- Minor** Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8**

2019-10-29 13:32

MOT test number

180389308260

Result**✗ Failed**

- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp x2 (4.2.3 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Position lamp not working x2 (4.2.1 (a) (ii))
- Fail** Offside Rear Seat belt not functioning as intended (7.1.2 (c))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #7

2018-08-06 10:03

MOT test number

819001632323

Result**✓ Passed**

- Advice** Nearside Front Inner edges

MOT #6

2018-08-04 13:46

MOT test number

900699867899

Result**✗ Failed**

- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Offside Obligatory mirror insecure (3.3 (b) (ii))



MOT #5	2017-08-08 09:36
MOT test number	153697617803
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt both

MOT #4	2017-08-08 09:36
MOT test number	250723194533
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Rear Child Seat fitted not allowing full inspection of adult belt both
Pass with rectification	Headlamp aim too low both sides (1.8)
Pass with rectification	Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #3	2016-06-21 13:36
MOT test number	973290603557
Result	✓ Passed
Advice	Os2 tyre walls deteriorating
Advice	Child seats fitted

MOT #2	2015-06-12 12:27
MOT test number	905813065168
Result	✓ Passed
Notice	Rear exhaust box outer casing deteriorating
Notice	Oil leak
Notice	Os2 tyre walls deteriorating 175 65 15
Advice	Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2014-06-13 12:48
MOT test number	337724464187
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2021

X

MOT

Expired:
19 February 2021

Tax status	Expired at 1 April 2021
Days left	1124 days too late
MOT expiry date	19 February 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-12-18
Last registration	2020-02-20
Complete history	See info



Registration #1	2010-12-18	6 mi
Registration #2	2014-06-13	67.054 mi
Registration #3	2015-06-12	82.665 mi
Registration #4	2016-06-21	97.491 mi
Registration #5	2017-08-08	115.220 mi
Registration #6	2017-08-08	115.220 mi
Registration #7	2018-08-04	130.916 mi
Registration #8	2019-02-20	146.602 mi
Registration #9	2019-02-20	162.288 mi
Registration #10	2019-02-20	177.974 mi
Registration #11	2019-02-20	193.660 mi
Registration #12	2019-02-20	209.346 mi
Registration #13	2019-02-20	225.032 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9632561
---------------	---------