



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI CREWVAN
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-14
Pictures	17
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	19
Total items failed	6

MOT #17	2023-08-10 09:28
MOT test number	395673718252
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Corrosion on rear brake discs
Advice	Nearside front tyre on 2.5mm
Advice	Nearside mirror repaired
Advice	Surface corrosion to rear

MOT #16	2022-04-20 10:33
MOT test number	971848058590
Result	✓ Passed

MOT #15	2021-08-18 11:11
MOT test number	894886592108
Result	✓ Passed
Advice	General underside corrosion

**MOT #14** 2020-05-14 09:02**MOT test number** 748901254055**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases front flexy joint (6.1.2 (a))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2019-06-07 14:57**MOT test number** 120723735749**Result** ✓ Passed**MOT #12** 2019-01-21 13:52**MOT test number** 270270882077**Result** ✓ Passed**MOT #11** 2019-01-08 14:12**MOT test number** 787901804396**Result** ✗ Failed**Fail** Offside Rear Brake hose connection leaking on a hydraulic braking system (1.1.12 (c) (ii))**Fail** Offside Driver's seat insecure (6.2.5 (a) (ii))**MOT #10** 2018-01-16 13:50**MOT test number** 712577384149**Result** ✓ Passed**MOT #9** 2017-04-18 13:27**MOT test number** 654575367992**Result** ✓ Passed

**MOT #8** 2016-07-06 13:02**MOT test number** 571716240982**Result** ✓ Passed**MOT #7** 2015-07-23 15:08**MOT test number** 558844505259**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2014-08-14 09:06**MOT test number** 636226324295**Result** ✓ Passed**MOT #5** 2013-08-16 15:22**MOT test number** 785958523202**Result** ✓ Passed

**Notice** E.M.L indicates a fault

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #4** 2013-08-16 11:17**MOT test number** 656188223270**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Headlamp aim too high (1.8)**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** E.M.L indicates a fault**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #3** 2012-08-15 16:03**MOT test number** 215468722210**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Upper Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2011-09-09 15:08**MOT test number** 885982551241**Result** ✓ Passed**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #1** 2011-09-09 15:08**MOT test number** 476132851241**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
9 August 2024

<b>Tax status</b>	Valid until 1 August
-------------------	----------------------

<b>Days left</b>	94
------------------	----

<b>MOT expiry date</b>	9 August 2024
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	WV58WHA
Plate since	2019-06-29
Current registration	WV58WHA
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-17
Last registration	2023-08-10
Complete history	<a href="#">See info</a>



Registration #1	2008-10-17	11 mi
Registration #2	2011-09-09	34.269 mi
Registration #3	2012-08-15	48.973 mi
Registration #4	2013-08-16	62.351 mi
Registration #5	2013-08-16	62.351 mi
Registration #6	2014-08-14	77.995 mi
Registration #7	2015-07-23	92.337 mi
Registration #8	2016-07-06	103.135 mi
Registration #9	2017-04-18	112.488 mi
Registration #10	2018-05-20	121.277 mi
Registration #11	2019-05-20	131.277 mi
Registration #12	2020-05-20	141.277 mi
Registration #13	2021-05-20	151.277 mi
Registration #14	2022-05-20	161.277 mi
Registration #15	2023-05-20	171.277 mi
Registration #16	2024-05-20	181.277 mi
Registration #17	2025-05-20	191.277 mi
Registration #18	2026-05-20	201.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1287 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Engine number	2475072